

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 28-29

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/15/67

WITNESSES TO CORNER..... 10" Jack Pine (1/4 S NBT) N10°W 19.0'



9" B. Oak (1/4 S NBT) S19°E 24.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced from one probable P.T.; bearing
S12°W 33 Links. Remains of Y. Pine stump, badly
burned.

Corner lies 1.00 chain south of trail road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 10/25/67