MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECOPO

JOB NUMBER: 94030 SHEET NO. : 1-496

MARQUETTE

(County)

For corners in

LAND CORNER RECORDATION CERTIFICATE Filin

7089 JAN, 28, 1971 FYISED MAY 14, 1975 REVISED JAN., 1983

LAND COR	NER RECORDATION CERTIFICATE	1994 DEC 28 PM 5: 57
Filing Requ	irement of Act 74, Mich. P.A. 1970) 1004 DEC 20 FM 5: 5/
Located In:	Corner Code ##	Patricia a. Monley

	1			(24 L2)	1110 61 7
1.	Public Land Survey T 47N R 27W J-13 T 46N R 27W J-1)				·
	T R				
	T R				
2.	Property Controlling S T R				~~
	in Section S T R		LIBER	1 PACE 1	65
3.	Miscellaneous S T R	Register (of Deeds Sta		
	Property in Sec. S T R				
4	Lot No, Recorded Plat	•	÷		
	Private Claims	— <u>}</u>	BCDE	FGHI	J K L
٥.		2	6	-43	
		3			
		4	<u> </u>	- 0 - 1 - 1 - 1	_1112_
	GERALD W. CARLSON , in a field survey on _ Tuesday, December 20 , 19 94	5			
do	hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	6			
in I	ines 1 and 2 above were in conformance with regulations and rules therefore as required in the	[_	18-17-1-	-1615	1413
	rent manual of survey instructions of the United States Department of the Interior, Bureau of Land	7	╂╼╂╼╂╌╂╌	++++	
	nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	8	1920	-2122	2324
	urt of Law; established, re-established, monumented, re-monumented, recovered, found as	9	+ + + +	-ill l	
	ressed below:	10	3029	-2827	2625
NO	TE: Not more than 4 corners, all in the same town and range, may be recorded	11			
	on this certificate.	12	3,3,	72 74	
	· · · · · · · · · · · · · · · · · · ·	13			33 30
A.	Description of original monument and accessories and/or subsequent restoration:				
	J-13: 1/4 Corner common to Section 2, T46N-R27W and				
	Section 35, T47N-R27W.				
	1846: Austin Burt's original survey notes describe the				
	corner monument as a Sugar post referenced by:				
	7" Sugar N59E 44 l				
	36" White Pine N21W 38 1	}			
B.	Description of corner evidence found and/or method applied in restoring or reestablish	ing corner	:		
	1994: Corner position established equidistant and on line between the Southwest and Distances West and East are 2665.164.	Southeast	Corners of	Section 35.	
	Group for the section of the section				
			RATIFIED	BY PEER (GROUP
			P.A. 345 C	F 1990	_
			Lim	n Als	Sussan
			DATE 7	Sa 1/2 16	agui
			UA I C	4. 6. 1. 1	<i>(</i>
Э.	Description of monument for corner and accessories established to perpetuate locating	the positi	on of the co	rner:	
	1994 - Set a 2 1/2' long 3/4" iron capped with a 3 1/4" diameter aluminum tablet Marq	uette Coun	tv Survey	•	
	Monument stamped to identify the corner referenced by nails in:				
	5" Ironwood N19E 15.92 ft.				
	7* Maple S42E 17.82 ft.				•
	8" Maple \$15W 40.60 ft.				
	7" Maple N78W 25.08 ft.		_	THE STATE OF	X
	Steel sign post South 1.0 ft.		المجح	LE OF WICH	18.3
	Monument is set flush with ground, concreted into a rock that is 0.50° below ground.		B. T	-	N. A.
	Bk. 8, Pg. 55			GERALD W.	***
			<i>#</i> 31	CARLSON	} ★ \\
				SURVEYOR	; * /
	11 000 00 1		8 <u> </u>	No.	I.B
ian	ed by Gueld a Carlson Date 12-2	-4-74	NE	24589	188

24589

Surveyor's Michigan License No. __