

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 .. NR. 28 .. W

. M a r q u e t t e COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 34 and 35

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" J. Pine (1/4s NBT) S 8° W 18 Links

9" J. Pine (1/4s NBT) N 80° E 26 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by unknown surveyor. Found 5/8" Iron Pipe in place. Found no evidence of original corner.

Corner was placed and witnessed May 17, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 5/23/60
REGISTERED LAND SURVEYOR
Billy D. Buckler