CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N.R. 28W

DESCRIPTION OF CORNER 1/4 corner bet. secs. 10-11

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5/5/67

WITNESSES TO CORNER..... 8" Jack pine (1/4 S NET) S86°W 59.2°

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

AND

CIRCLE CORNER REGISTERED

This corner replaced at site of a 30" white pine, down and in poor condition. Found remains of a 24" white pine, bearing N48°W, 29 links, for possible bearing tree.

Found no evidence of marks on either tree.

SURVEYOR'S SEAL

Billy D. Buckler

DATE May 26, 1967