## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Corners III					
Ţ	Rarquette (County)	Localed in:			Corner Code //	
1	Public Land Survey		T	46N	R 28W	27
			1		R.	
			Ţ		R	
			Ţ		R	
2	Property Controlling	S 17	Ţ		R	7
	in Section	s	1		R	
3	Miscellaneous	S	T		R	
	Property in Sec	S	T		R	

Register of Deeds Stamp & File Number


- 4 Lot No , Recorded Plat
- 5 Private Claims
- 3. Keith Sackett in a field survey on Barch 5 in 91 91 in defenting the survey of Barch 5 in 19 91 in defenting the survey of the survey of the survey in survey in survey in survey in survey in the survey in survey i

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Toriginal monument and accessories not found. Found subsequently, apparently.

1 1/4" ID x unknown length iron pipe.



B. Description of corner evidence found and/or method applied in restoring or reastablishing corner.

Restored at iron pipe. Local resident George Svanson says pipe has been in place for 55 years.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

F7
Restored at found iron pipe
5" balsam S35K 4.6' S21 MBT
4" balsam S86W 12.7' S20 MBT
3" balsam M10W 14.6' S17 MBT
10" j. pine M39K 8.4' 1/16s BT
10" j. pine S32K 17.9' 1/16s
BT
12" j. pine S28W 19.9' 1/16s

REPUT L SCREET TO COMMENT TO COMM

Signed by Kell Jacket

Date

March 15, 1991

Surveyor's Michigan License No

19006

FORM APPROVID BY MICHMEAN STATE BOARD OF LAND BURVEYORS, JAN. 20, 1871 REVISED MAY 14, 1875 REVISED JAN. . 1862