

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

T	Marquette <small>(County)</small>	Located In	Corner Code //
1.	Public Land Survey	T 46M R 28W	E9
		T R	G9
		T R	G10
		T R	G11
2.	Property Controlling in Section	S T R	
		S T R	
3.	Miscellaneous Property in Sec	S T R	
		S T R	
4.	Lot No	Recorded Plat	
5.	Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	1	2	3	4	5	6	7	8	9	10	11	12	13
3	14	15	16	17	18	19	20	21	22	23	24	25	26
4	27	28	29	30	31	32	33	34	35	36	37	38	39
5	40	41	42	43	44	45	46	47	48	49	50	51	52
6	53	54	55	56	57	58	59	60	61	62	63	64	65
7	66	67	68	69	70	71	72	73	74	75	76	77	78
8	79	80	81	82	83	84	85	86	87	88	89	90	91
9	92	93	94	95	96	97	98	99	100	101	102	103	104
10	105	106	107	108	109	110	111	112	113	114	115	116	117
11	118	119	120	121	122	123	124	125	126	127	128	129	130
12	131	132	133	134	135	136	137	138	139	140	141	142	143
13	144	145	146	147	148	149	150	151	152	153	154	155	156

I, **Keith Sackett**, in a field survey on **October 12**, 19**90**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration.**

E9	G9	G10	G11
Original monument and accessories not found.	Original monument and accessories not found.	Original monument and accessories not found.	Original monument and accessories not found.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.**

E9	G9	G10	G11
Restored at Dave Erickson's corner.	Restored at Dave Erickson's corner.	Restored at Dave Erickson's corner.	Restored at Dave Erickson's corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.**

E9	G9	G10	G11
Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245 witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:
7" j. pine S73E, 27.98' 8" j. pine S18W, 11.60' 14" j. pine N77W, 64.12' 14" j. pine N51W, 13.34'	4" spruce N73E, 14.31' 8" j. pine S56E, 44.65' 4" tamarack S17W, 25.11' 5" j. pine N78W, 29.18'	10" j. pine N35E, 12.54' 6" j. pine S44E, 63.77' 9" j. pine S32W, 42.52' 8" j. pine N76W, 27.35'	9" j. pine N50E, 72.24' 9" j. pine S52E, 38.76' 12" j. pine S3W, 53.18' 11" j. pine S50W, 70.79'

Signed by *Keith Sackett*  
 Surveyor's Michigan License No 19006

Date

