

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

1	Marquette <small>(County)</small>	Located In:	Corner Code //
1.	Public Land Survey	T 46N R 28W	E10 E11 F9 F11
2.	Property Controlling in Section	S T R	
3.	Miscellaneous Property in Sec	S T R	
4.	Lot No	Recorded Plat	
5.	Private Claims		

Register of Deeds Stamp & File Number

I, **Keith Sackett**, in a field survey on **October 10**, 19**90**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2												
3												
4												
5												
6	16	17	18	19	20	21	22	23	24			
7												
8	16	20	21	22	23	24						
9												
10	30	28	29	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A Description of original monument and accessories and/or subsequent restoration

E10	E11	F9	F11
Original monument and accessories not found.	Original monument and accessories not found.	Original monument and accessories not found.	Original monument and accessories not found.

B Description of corner evidence found and/or method applied in restoring or reestablishing corner.

E10	E11	F9	F11
Restored at Dave Erickson corner.	Restored at Dave Erickson corner.	Restored at Dave Erickson corner.	Restored at Dave Erickson corner.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E10	E11	F9	F11
Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:	Set a 5/8" x 36" rebar v/plastic cap marked "D. Erickson L.S. No. 29245" witnessed by 6" spikes v/washers marked "29245" in:
7" tamarack N55E 52.50' 5" tamarack S55W 9.57' 6" tamarack N58W 23.49' 5" spruce N4E 15.69'	6" spruce N60E 18.92' 4" tamarack S2E 11.71' 4" spruce S60W 5.27' 6" tamarack N13W 12.86'	8" j. pine N4E 7.27' 17" r. pine S45E 55.85' 11" j. pine S19W 28.71' 10" j. pine N65W 33.02'	7" balsam (double) S66E 35.89' 10" v.birch S6E 40.92' 5" sugar maple S68W 9.44' 5" j. pine N14W 26.83'

Signed by

Keith Sackett

Date

January 10, 1991

Surveyor's Michigan License No

19006

STATE OF MICHIGAN
 DEPARTMENT OF LAND SURVEYORS
 FORM APPROVED BY MICHIGAN BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1978
 REVISED JAN. 1983