LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

I. Keith I. Sackett do hereby cettly that under requirements of P.A. 74, Michigan P.A. of the corner points mentioned in lines I and 2 above were, in a field survey on. See_below 19 established, monumented, recovered or extractions of the United States Department of the Corner of	1. PUBLIC LAND SURVEY. 1. 46 . R 28 . C3, B3, C7. 2. PROPERTY CONTROLL. 1 . R. R	
2. PROPERTY CONTROLL INCLUSION. 3. MASCELLANDOUS PROPERTY IN SECTION. 1. N. R. 4. LOT NO. RELORDED PLAT 5. PRIVATE CLAIMS RECORDED PLAT 1. Keith 1. Sackett do hereby certify that under requirements of P.A. 74, Michigan P.A. of the corner points mentioned in low-1 and 2 above were, in a field survey on. See Delow. 10. estable and nonemented to the current musual of survey instructions of the United States Department of the low and rules therefore as required in the current musual of survey instructions of the United States Department of the low Bureau of Land Management on by a decree of a count of law. 10. found, recovered, restored, established or re-estable and survey owner, in a field survey on. 10. found, recovered, restored, established or re-estable and surveyors of the United States Department of the Internations of Corner C3: Original monument and accessories not found. Corner G3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner C7: Original monument and accessories not found. B. Description of concer evidence found and/or method applied to restoring or re-establishing corner: Corner C3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner C3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C4: Set 1" I.D. by 32" Iron Pipe w/4" Corner C5: Set 1" I.D. by 32" Iron Pipe w/4" 11" Signed B74 State I.D. by 32" Iron Pipe w/4" 24" w., pine MOE, 3.5 of t. S.1, NBT 16" maple S74E 13.1 ft. S8, NBT 17" maple S85E 17. ft. 1/45, NBT 18" maple NG2E 32.1 ft. 1/45, NBT 19" maple S65E 17. ft. 1/45, NBT 29" maple NG2E 32.1 ft. 1/45, NBT 20" spruce N74W 41.4 ft. 1/45,	2. PROPERTY CONTROLL ING IN SECTION. 3. MISCELLANFOUS PROPERTY IN SECTION. 4. LOT NO. RECORDED PLAT 5. PRIVATE CLAIMS L. Keith I. Sackett	
A. LOT NO	4. LOT NO. RECORDED PLAT 5. PRIVATE CLAIMS L. Keith L. Sackett do hereby certify that under requirements of the corner points mentioned in lines 1 and 2 above were, in a field survey on. See Dellow re-established, monumented, re-monumented, recovered or restoned as expressed below and in and rules therefore as required in the current mutual of survey instructions of the United State Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner paids above were, in a field survey on. 19 found, recovered, restoned as expressed below and in conformance with the rules of the Michigan State Board of Registrat Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Corner C3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing Corner C3: Restored 10-5-83 by double proportion between corner fits reasonable with section corner west. Corner B3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 14" w. pine NdE, 6" maple S8W 20.6 ft. S7, NBT 14" w. pine NdE, 6" maple S74E 13.1 ft. S8, NBT 9" w. pine S28E, 20 Corner R3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 11" balsam S72W 2: 9" w. pine S28E, 20 Corner R3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 11" w. pine NdE, 6" maple S74E 13.1 ft. S8, NBT 9" w. pine S28E, 20 Corner R3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 11" w. pine NdE, 6" maple S74E 13.1 ft. S8, NBT 9" w. pine S28E, 20 Corner R3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 11" w. pine NdE, 6" maple S74E 13.1 ft. S8, NBT 9" w. pine S28E, 20 Corner R3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 11" w. pine NdE, 6" maple S74E 13	
A LOT NO	A LOT NO	
1. Keith I. Sackett do bereby certify that under requirements of P.A. 74, Michigan P.A. of the corner points mentioned in lines I and 2 above were, in a field survey on. See below 19. A 74, Michigan P.A. of the corner points mentioned in lines I and 2 above were, in a field survey on. See below 19. See below	I. Keith L. Sackett do bereby certify that under requirements of the corner points mentioned in lines 1 and 2 above were, in a field survey on see below re-established, monumented, re-monumented, recovered or restored as expressed below and in and rules therefore as required in the corner manual of survey instructions of the United State Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner and 5 above were, in a field survey on 19 found, recovered, restor as expressed below and in conformance with the rules of the Michigan State Board of Registrat Docree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Corner C3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Found kn high 1.50 chains west of corner as per original notes. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing Corner C3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 6" maple S74E 13.1 ft. S8, NBT 10" maple S74E 13.1 ft. S8, NBT Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C4: Set 1" I.D. by 32" Iron Pipe w/4" Corner C5: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" Alum. cap.	
I, Keith I. Sackett do berchy certify that under requirements of P.A. 74, Michigan P.A. of the corner points mentioned in lines 1 and 2 above were, in a field survey on. See, below. 19 established, monamented, remonented, recovered or restored as expressed below and in conformance with regular and rules therefore us required in the corner annual of survey instructions of the United States Department of the fore Bureau of Land Management or by a derive of a count of law. Furthermore, that the corner points mentioned in lines and 5 above were, in a field survey on. 19 found, recovered, restored, established or re-established below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, Decree of a Court of law: A. Description of original monument and accessories not found. Corner 03: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner C7: Original monument and accessories not found. Corner C8: Original monument and accessories not found. B. Description of conser evidence found and/for method applied in restoring or re-establishing corner: Corner C3: Restored 10-5-83 from land calls west and section corner as and land calls. Corner B3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner C7: Set 1" 1.0. by 32" Iron Pipe w/4" Corner C7: Set 1" 1.0. by 32" Iron Pipe w/4" alum. cap. 10" maple S74E 13.1 ft. S8, NBT 10" maple S74E 13.1 ft. S8, NBT 24" maple NaSE 13.8 ft. S5, NBT 29" w. pine S28E, 30.0 ft. S20, NBT 20" maple S64E 17.7 ft 1/45, NBT 24" maple N62E 32.1 ft 1/45, NBT 25 maple S64E 17.7 ft 1/45, NBT 25 maple S64E 17.7 ft 1/45, NBT 25 maple S64E 17.7 ft 1/45, NBT 26 maple S74E 17.7 ft 1/45, NBT 27 maple S64E 17.7 ft 1/45, NBT 28 UNVEYORS MICHIGAN REGISTRATION NO. 10 DATE. SURVEYORS MICHIGAN REGISTRATION NO. 10 DATE. SURVEYORS MICHIGAN REGISTRATION NO. 10 DATE. SURVEYORS MICHIGAN REGISTRATION NO.	I. Keith I. Sackett	
the corner points mentioned in line 1 and 2 above were, in a field survey on. See, bellow. 19 establish re-established, monumented, recovered or re-breed as expressed below and in conformance with regular and survey instructions of the United States Department of the Interest manual of survey instructions of the United States Department of the Interest manual of survey instructions of the United States Department of the Interest manual of survey instructions of the United States Department of the Interest of States Department of the Interest of the United States Department of the Interest of States Department of States Departme	the corner points mentioned in lines 1 and 2 above were, in a field survey on See below re-established, monumented, re-monumented, recovered or restored as expressed below and in and rules therefore as required in the corrent manual of survey instructions of the United State Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner and 5 above were, in a field survey on	REGISTER OF DEEDS STAMP AN
Corner C3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and for method applied in restoring or re-establishing corner: Corner C3: Restored 10-5-83 by double proportion between corners and land calls. Corner B3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with land calls. Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C4: Set 1" I.D. by 32" Iron Pipe w/4" Corner C5: Set 1" I.D. by 32" Iron Pipe w/4" Corner C6: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" I.D. by 32" Iron Pipe w/4" Cor	Corner C3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Corner B3: Original monument and accessories not found. Found kn high 1.50 chains west of corner as per original notes. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and for method applied in restoring or re-establishing Corner C3: Restored 10-5-83 by double proportion between corner Corner B3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 14" w. pine N40E, 11" balsam S72W 2: 9" w. pine S28E, 20 Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 14" w. pine S28E, 20 Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 30 w. pine S28E, 30 corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 30 w. pine S28E, 30 corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 31 cap. 32 cap. 32 cap. 33 cap. 33 cap. 34 cap. 35 cap. 35 cap. 36 ca	ites Department of the Inte points mentioned in lines is red, established or re-establis
Corner B3: Original monument and accessories not found. Found knob of granite 15 ft high 1.50 chains west of corner as per original notes. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and for method applied in restoring or re-establishing corner: Corner C3: Restored 10-5-83 by double proportion between corners and land calls. Corner B3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with land calls. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Corner C7: Restored 10-24-83 by double proportion. Fits good with land calls. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Corner C7: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 11" balsam S72W 23.5 ft. S19, NBT 12" maple N62E 32.1 ft 1/4S, NBT SIGNED BY DATE SURVEYORS MICHIGAN REGISTRATION NO. FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE.	Corner B3: Original monument and accessories not found. Found kn high 1.50 chains west of corner as per original notes. Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing Corner C3: Restored 10-5-83 by double proportion between corner Corner B3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 10" maple S83W 20.6 ft. S7, NBT alum. cap. 10" maple S74E 13.1 ft. S8, NBT alum. cap. 4" maple N38E 13.8 ft. S5, NBT 9" w. pine S28E, alum. cap.	
high 1.50 chains west of corner as per original notes. Corner C7: Original monument and accessories not found. B. Description of corner exidence found and/or method applied in restoring or re-establishing corner: Corner C3: Restored 10-5-83 by double proportion between corners and land calls. Corner B3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with land calls. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 6" maple S74E 13.1 ft. S8, NBT 11" balsam S72W 23.5 ft. S19, NBT 11" balsam S72W 23.5 ft. S19, NBT 11" balsam S72W 23.5 ft. S20, NBT Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 7" maple S54E 17.7 ft 1/4S, NBT 12" maple N62E 32.1 ft 1/4S, NBT 12" maple N62E 32.1 ft 1/4S, NBT 24" spruce N74W 41.4 ft. 1/4S, NBT SIGNED BY. DATE DATE DATE DATE DATE DATE DATE	Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing Corner C3: Restored 10-5-83 by double proportion between corner Corner B3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 14" w. pine N40E, 11" balsam S72W 2: 9" w. pine S28E, 20 Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" 9" w. pine S28E, 20 Corner B3: Set 1" I.D. by 32" Iron Pipe w/4"	
Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner C3: Restored 10-5-83 by double proportion between corners and land calls. Corner B3: Restored 10-5-83 from land calls west and section corner east. It also fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with land calls. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner C7: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 6" maple S74E 13.1 ft. S8, NBT 14" w. pine N40E, 35.6 ft. S17, NBT 11" balsam S72W 23.5 ft. S19, NBT 24" maple N38E 13.8 ft. S5, NBT 9" w. pine S28E, 30.0 ft. S20, NBT Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 12" maple S54E 17.7 ft 1/4S, NBT 12" maple N3EE 32.1 ft 1/4S, NBT 12" maple N3EE 32.1 ft 1/4S, NBT 24" spruce N74W 41.4 ft. 1/4S, NBT SIGNED BY DATE DATE DATE	Corner C7: Original monument and accessories not found. B. Description of corner evidence found and/or method applied in restoring or re-establishing Corner C3: Restored 10-5-83 by double proportion between corner Corner B3: Restored 10-5-83 from land calls west and section corner fits reasonable with section corner west. Corner 7: Restored 10-24-83 by double proportion. Fits good with Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 14" w. pine N40E, 11" balsam S72W 2: 4" maple N38E 13.8 ft. S5, NBT 9" w. pine S28E, 20 alum. cap. 20 Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" 20 w. pine S28E, 20 alum. cap.	nob of granite 15 ft
Corner 7: Restored 10-24-83 by double proportion. Fits good with land calls. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner C3: Set 1" I.D. by 32" Iron Pipe w/4"	Corner 7: Restored 10-24-83 by double proportion. Fits good with C. Description of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of monument for corner and accessories established to perpetuate locating the proportion of	rs and land calls.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner C3: Set 1" I.D. by 32" Iron Pipe w/4"	C. Description of monument for corner and accessories established to perpetuate locating the respect to the corner C3: Set 1" I.D. by 32" Iron Pipe w/4" Corner C7: Set 1" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 14" w. pine N40E, 11" balsam S72W 23 14" maple N38E 13.8 ft. S5, NBT 9" w. pine S28E, 11" Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap.	th land calls.
Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 6" maple S74E 13.1 ft. S8, NBT 4" maple N38E 13.8 ft. S5, NBT Corner B3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 7" maple S54E 17.7 ft 1/4S, NBT 12" maple N62E 32.1 ft 1/4S, NBT 24" spruce N74W 41.4 ft. 1/4S, NBT SIGNED BY DATE DATE DATE DATE DATE DATE DATE	Corner C3: Set 1" I.D. by 32" Iron Pipe w/4" alum. cap. 10" maple S83W 20.6 ft. S7, NBT 14" w. pine N40E, 6" maple S74E 13.1 ft. S8, NBT 11" balsam S72W 23 4" maple N38E 13.8 ft. S5, NBT 9" w. pine S28E, Corner B3: Set 1" I.D. by 32" Iron Pipe w/4"	
alum. cap. 7" maple S54E 17.7 ft 1/4S, NBT 12" maple N62E 32.1 ft 1/4S, NBT 24" spruce N74W 41.4 ft. 1/4S, NBT SIGNED BY SURVEYOR'S MICHIGAN REGISTRATION NO	🐩 alum. cap.	35.6 ft. S17, NBT
SURVEYOR'S MICHIGAN REGISTRATION NO FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE.	12" maple N62E 32.1 ft 1/45, NB1 24" spruce N74W 41.4 ft. 1/45, NBT	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE.	SIGNED BY DATE	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE.		
APPROVED AND SIGNED BY Cotto Lockett DATE 11-121 - 83	CHES OF SUDUSY PARTY	