

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 45-46 NR 29 W

Marquette

COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 2, 3, 34 and 35.

DESCRIPTION OF CORNER MONUMENT \_\_\_\_\_

WITNESSES TO CORNER 4" B. Spruce N 1 E 24 1/2 Links, "S 35 1BT)

4" B. Spruce S 87 W 23 Links, "S 3 1BT)

4" B. Spruce S 10 E 26 Links, "S 2 1BT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established east and west on Twp. Line between two meander corners. 1.79 chains east and 2.31 chains West. Checked north to meander corner 4.47 chains. Government notes indicate 4.40 chains.

Corner was placed and witnessed on 28 July 1958 with Crew.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 4-30-59  
REGISTERED LAND SURVEYOR