

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 23W


Marquette COUNTY

DESCRIPTION OF CORNER 4 Cor. bet. Secs. 13-24

CORNER MONUMENT 3/4" iron pin, buried in approx. 10 E-W road

DATE MONUMENT PLACED AND WITNESSED 4-13-67

WITNESSES TO CORNER..... 13" cedar (4S MBT) S20°E 64.6'



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found iron pipes bearing N30°E, 30'; N30°W, 30';
S30°E, 30' and S30°W 30'. from corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler, R.L.S. DATE 9-20-68
REGISTERED LAND SURVEYOR