MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_47 NR 25 W

DESCRIPTION OF CORNER Section Corner common to Sections 21,22,27,28	TY
DESCRIPTION OF CORNER MONUMENT_1" Pipe with 4" Brase cap	
WITTNESSES TO CORNER 4" 8. Maple = 8 4 F = 76 Links	
10" Jack Pine - 8 79 W - 64 Links	
8" Jack Pine - N 70 E - A7 Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division Survey crew, while working in this Township. One probable B.T. still in place, badly rotted.

Corner was placed and witnessed May 31, 1951.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 6/15/ 51_