For corners in

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUE	1411 27	1.3	
RECEIVED	FOR	RECORE)

1999 DEC 22 AN 11: 27

0,		/	
115 Think	1	CM	A
Contract the Rate Con	46.	Hon	RELLI
Patricia REGISTER	DF	DEED	1/2
	9,	MECRO	V 18-
			×

MARQU		Located In:	Corner Code #		REGISTER OF DEEDS
(Count	ry)				DEC 13 DA
1. Public Land Se	uřvey	T <u>47N</u> R <u>25W</u> T R T R	<u>G-13</u>		*
2. Property Cont in Section	S	TRTRTR			70 .0
3. Miscellaneous	· -	T R		·	LIBER ${f R}2$ page 22
Property in Se	ec. S_	T R		Pagietar	of Deeds Stamp & File Number
4 Lot No	Becord	ed Plat		Vehister	Or Deeds Stamp & File Number
5. Private Claims					
				A B C	DEFGHIJKL
				2 6	-5 -4 -3 -2 -1
				_ 3	
		, in a field survey on		9_,	8 9 10 11 12
			gan P.A. of 1970, the corner paint ith regulations and rules therefor		-8
			ited States Department of the Inte		
Bureau of Land Ma	nagement or by	a decree of a Court of	f Law and/or that the comer pe	oints 6 18	-1716151413
			th the rules of the Michigan Boar		
			olished, re-established, monumer	nted, 8 19-19-	-2 ['] 02 ['] 12 ['] 22 ['] 32 ['] 4-
recovered, found as	expressed below	/;		9	
NOTE: Not more	than 2 corner	s, all in the same town	and range, may be recorded	10-30	29 28 27 26 25
on this ce	ertificate.		• ' -	11	
				12 31	32 33 34 35 36
			nd/or subsequent restoration: 25W on the South Township I		
	Burt's original t	ownship boundary surv nced by:	vey notes describe the corner pen N74W, 36L	RATIFIE	D BY PEER GROUP 5 OF 1990
(SEE REVERSE SID	E)			-Xa	my y Johnson
				DATE	1 11/1/49
G-13: 1999: No or Measured existing 10" Jack Pine (de	iginal corner e references: ad and fallen) West, 7.50 ch	vidence found. Found a N18E, 29 nains, top of hill (495')	I applied in restoring or reestand accepted a 4" brass tablet 0.2' to center (Buckler NBT), with hip chain we measured	: oa 1 1/4" iron pipe	projecting 1.2' above ground
G-13: 1999: The n	nonument is a MCR 1999" and S24W, 18 S86E, 19				of the comer: nund. We stamped the existing
Measured Existing 10" White Birch 9" Aspen	N85W, 13	3.73' (Buckler NBT-196 3.10' to found nail (Buc			
Green Steel Sign P	ost w/ Yellow	Survey Marker Sign	N12E, 3.05		
Note: Bearing trees Bk. 12, Pg. 88	s have painted T46N-R25W		il blazes, d.h. measuring nails, Corner Search Sheet	, and stamped B.T. 99100	Tags affixed.
				4	GIVE OF WICHIGAD

GERALD W CARLSON SURVEYOR No.

Surveyor's Michigan License No._

12-8-99

PART A CONTINUED:

1959: A Land Corner Record by Billy Buckler, P.S. #08887, indicates a 1" pipe with a 4"brass cap with the following references:

10" J. Pine (S 34 NBT)

N20E,

5"

White Birch (S 33 NBT)

44 L

7" Aspen (S 3 NBT) S50E, 15L
Billy States: "This corner was replaced at an old wood stake. Stake appears to be in line with E-W road 1/4 mile to the East. No evidence of original comer. Corner was placed and witnessed July 14, 1959."

1984: A section breakdown sheet by Gerry Carlson, P.S.# 24589, indicates the corner distance N89-32-15W, 5274.27' to the Southeast corner and distance NOO-09-06E, 5351.53' to the Northwest corner of Section 34.

1986: Sundberg, Carlson and Associates, Inc. survey notes, indicate a corner (no description of the monument) with the following found references:

10" W. Birch 8" Aspen

N63E, S47E.

10.13' (Dept. of Conservation NBT)

8" Birch

N82W,

13.80' (Dept. of Conservation NBT)

9" J. Pine

N20E,

29.25' (Dept. of Conservation NBT)

1990:A section breakdown sheet by Gerry Carlson, P.S. # 24589, indicates the corner distance S89-35-27W, 5264.67' to the Southwest corner of Section 33.

SECTION