## SURVEY & REMONUMENTATION

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

JOB NUMBER: 94030 SHEET NO. : 1-518 APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 28 PM 5: 58

4. Lot No. \_\_

5. Private Claims \_

COMMISCION

\_\_\_\_\_, Recorded Plat

Conners III COM	11 X (1 2 5 5 1 5 5 1 4		$\mathcal{M}_{\mathcal{U}}$ , $\mathcal{M}_{\mathcal{U}}$ , $\mathcal{M}_{\mathcal{U}}$
MARQUETTE (County)	Located In:	Corner Code ##	REGISTER OF DEFES
Public Land Survey	T <u>47N</u> R <u>26W</u> T R T R	E1	
• •	T R S T R		i 4
Miscellaneous	S T R S T R S T R	<u> </u>	LIBER $1$ PAGE $184$ Register of Deeds Stamp & File Number
	Property Controlling in Section	MARQUETTE   Located In:	MARQUETTE (County)         Located In:         Corner Code ##           Public Land Survey         T 47N R 26W E1         E1           T R R TR         TR           Property Controlling S T R In Section S T R         TR           Miscellaneous S T R         TR

I, GERALD W. CARLSON in a field survey on Tuesday, December 27 , 1994
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

## NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-1: Section Corner common to Sections 4 and 5, T47N-R26W. 1962: Survey drawing by Walter H. Knapp, Milwaukee for 1845: Sam Hill's original survey notes described a corner Cleveland Cliffs and recorded in Liber 248, Page 482 monument as a wood post 37 1 East of the Corner common to indicates Northeast Corner of Section 5 as 18.15' East

Sections 32 and 33, T48N-R26W, referenced by: 8" Birch. S38E. 36 l

Cedar. S64W, 21 1

No date given: Maas Triangulation Coordinates give Northeast Corner of Section 5 as S2.98 and 5299.12E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted a 1 1/2" iron pipe on R.R. grade. Distance West is 2620.87' and distance East is 2633.47'.

RATIFIED BY PEER GROUP

P.A. 345 OF 1990

10

11

12

of the centerline of the railroad. No corner accessories

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced a 1 1/2" diameter iron pipe with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

given.

6" White Birch S56E 107.81 ft.

9" White Pine 874E 114.15 ft.

6" Jack Pine N52E 142.26 ft.

5" White Spruce N42W 36.12 ft.

1.91 ft. Steel sign post S60E

Steel sign post S60E 1.71 1L.

Monument is located on the Southerly slope of an active R.R. grade and is set flush with the ground

Suald W Carlos Signed by \_

\_\_\_\_\_ Date 12-28-94

GERALD W. CARLSON SURVEYOR No. 24589 POFFS 104?

Burveyor's Michigan License No. \_\_

24589