MARQUETTE COUNTY MICHIGAR RECEIVED FOR RETORD

JOB NUMBER: 95053 SHEET NO. : 1-618

APR 0 1 1996 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	1995	DEC	27	AH	7:	4	L
--	------	-----	----	----	----	---	---

Fo.	r corners in COM	MISSION	Corner Code #
1.	Public Land Survey	147N R26W	M-3 /
2	Proporty Controlling	T R T R S T R	
۷.	Property Controlling in Section	STR	

1 Mr. 236

Property in Section S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	
	2 5 5 5 1 4 3 - 2 - 1 - 3
I, GERALD W. CARLSON , in a field survey on Wednesday, August 23 , 1995 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention	4 - 7 - 8 - 9 - 10 - 11 - 12 - 5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the curremanual of survey instructions of the United States Department of the Interior, Bureau of La Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 a	ent and 7
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, four as expressed below:	ya
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11
A. Description of original monument and accessories and/or subsequent restoration:	
M-3: Section Corner common to Sections 1 and 12, T47N-R26W 18" Y. Birch S43W, and Sections 6 and 7, T47N-R25W. 1844: William A. Burt's 1947: MCRC notes from	33.6' F.B. 601, pp. 152-153, indicate that

original survey notes describe the corner monument as a wood old B.T., 20" Sugar S82W, 18 L, is still standing and post referenced by: 20" Sugar S82W, 18 1

growing, but other old Sugar B.T. is gone. Set Iron Pipe and Balsam post in mound of stones. Set reference:

12" Sugar N33E, 20 1 No Date: MCRC notes from F.B. 517 (No pg. # - 3/4 into book) indicate the corner as a set 3/4" circular iron pin, Called

30" Y. Birch S60E, 11.5'; Found references: Y. Birch Stump S42W,

Sugar Stump S08E, 30.1

old B.T.'s good, but did not list them. Set new B.T.'s: 1965: The corner is indicated on an unrecorded Upper Pen-12" Maple Stump SOSE, 30.1' insula Power Company R.O.W. map. (See Reverse Side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found and accepted a 1" iron pipe, bent over, as previously found by G. Carlson in 1988. Distance South is 5254.76', and Distance North is 2627.93'.

RATIFIED BY PEER GROUP

GERALD W. CARLSON SURVEYOR No.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

1995:	Replaced	found	iron pipe	with	a 2	3/8"	0.D.	aluminum	pipe	capped	with a	a 3 1/	4 "	aluminum	tablet	Marquette	County
Survey	Monument	, flus	sh with gr	ound,	and	stamp	ed to	identify	the	corner.	. Refe	renced	lЪv	aluminum	nails	set in:	-

11" S. Maple

N3OE, 16.74

8" S. Maple

N74E. 27.27

7" S. Maple 6" B. Cherry

S40E,

N66W.

Green Steel Sign Post w/Survey Marker Sign

\$39W, 1.75

Note: Monument leans slightly East due to large rock below the surface. Corner is +/- 175' North of C/L of old Co. Rd. 480.

Bk. 10, pp. 1-4.

Devola a Calser

≣urveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Record No. 618:

Part A Continued:

No Date: The corner is shown on an easement map for Northern Natural Gas Company recorded in L. 72, MR Pg. 585.

No Date: The corner is indicated on an easement map recorded in L. 289, Deeds Pg. 186.

No Date: The corner is indicated on an easement map recorded in L. 290, Deeds Pg. 224.

No Date: The corner is indicated on an easement map recorded in L. 290, Deeds Pg. 272.

1976: An LCRC recorded by George B. Wilson RLS #17607, in L. 1, RC Pg. 141, indicates the corner as a found 16" X 10" quartz stone, rectangular on top, nested in a group of stones. Bearing trees notched facing corner. Iron pipe lying horiz. on top of ground next to stone. No other evidence found. Established references:

10" Maple

N28E.

16.4'

8" Maple

S38E,

12.3'

1989: The corner is indicated on an Easement Description Map for Wisconsin Electric recorded by Sundberg, Carlson, and Associates in L. 130, MR Pg. 755. No accessories given.