SURVEY & REMONUMENTATION

JOB NUMBER: 94030

LAND CORNER RECORDATION CERTIFICATE

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECOUNT

1994 DEC 28 PH 5: 57

SHEET	NO	1 507

For corners in

APR 28 1995

Filing Requirement of Act 74, Mich. P.A. 1970

0	r corners in	. 20 1000			F			1	24.		. /	<i>/</i> .		
	MARQUETTE (County)	MMISSION ^{ed}	In:	Corner Code#				UZ	itais TEGIS	8222 750	4.5 or i	Ups	elez	ور کارک
1.	Public Land Survey	T T	_ R <u>27W</u> _ R _ R	M-5				•	1210	12.45.3	ut 1	и і п	S (/	4,
2.	Property Controlling in Section	S T	_ R				LIBER		1	_ PAG	:E1	73))	
3.	Miscellaneous				F	Register	of Dec	ds						
	Property in Sec.	S T	_ R		L									
4.	Lot No, i	Recorded Plat				A	в с	D	E F	G	ні	. . j	K L	м
5.	Private Claims						6	- 5 —	\perp		3	<u> </u>		
		•				3		Ĺ	\perp			$\sqcup \downarrow$	\perp	
				•		4		- - 8-	.	——₁	<u> </u>	 11-	<u> </u>	2—
	GERALD W. CARLSON	. in a field survey	on <u>Wednesd</u>	ay, December 21 , 1994	,	5	1	\bot	$\downarrow \downarrow$		\sqcup		_	L
do	hereby certify that under re	quirements of P.A. 74	, Michigan P.A	i. of 1970, the corner points me	ntioned	6	-18-	-17-	16		15	 14-	—₁	 3—
in I	lines 1 and 2 above were i	n conformance with	regulations a ł States Dena	nd rules therefore as required rtment of the Interior, Bureau	o in the of Land	7	11	_	$\bot \bot$		\sqcup	\vdash		ļ
Ма	nagement or by a decree of	a Court of Law and/o	r that the corn	er points mentioned in lines 3,	4 and 5	8	-19	 -20-	 -21		22	23-	a	4
ab	ove were in conformance w	ith the rules of the Mi	chigan Board	of Land Surveyors or by a Dec	ree of a	9	$\bot \bot$	1-	-	Д.	<u> </u>	lacksquare	-	<u> </u>
Co exi	ourt of Law; established, pressed below:	re-established, mon	iumentea, re-	monumented, recovered, fo	unu as	10	-30	29-		,;] 27—	26-	2	5—
			same town a	and range, may be recorde	ed	11	+	+		+		+	 	
	on this certificate	•				13	-37	-32-	33]			Ĺ
Α.	Description of original	monument and ac	cessories ar	nd/or subsequent restoration	on:				-					

M-5: NE Corner of Section 13.

1844: William A. Burt's original survey notes describe the

corner monument as a post referenced by:

16" Sugar S62E 7 1

N54W 33 1 10" Fir

1845: Sam Hill's original subdivision survey notes for

the NW Corner of Section 18, T47N-R26W

8" Hemlock N27E 10 l

17" Sugar S55E 08 1

1913: C.C.I. Company coordinate list for NE Corner of Section 13 indicates an iron pipe with coordinates South 10342.34 and West 4897.63.

No date given: MAAS coordinates for SE Corner Section 12, T47N-R26W indicate the following additional references for T47N-R27W indicates South 10342.34 and West 4897.63.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner position calculated from early 1900 Maas Mine coordinate values from two found corners 1/2 mile North and South. Distance South is 2626.20' (2626.87' Maas) and distance North is 2611.71' (2612.62' Maas).

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 3/4" re-rod grouted in rock capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

12" Twin Maple NOSW 33.08 ft.

N33E 50.82 ft. 7" Hemlock

5" Balsam S50E 23.19 ft.

4" Maple S24W 32.20 ft.

Steel sign post West 7.4 ft. Monument is 0.30' above ground and set in a rock knob.

Bk. 8, Pg. 71

Gerald W Carleon Signed by __ Surveyor's Michigan License No. 24589

SURVEYOR No. 24589

GERALD W.

CARLSON

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975