## **MICHIGAN** DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T46-47 NR 28 W

	_ Earquette COUNT
DESCRIPTION OF CORNER Section corner common to Se	ctions 1, 2, 35 and 36.
DESCRIPTION OF CORNER MONUMENT_1" Pipe with 4"	Brass Cap.
WITNESSES TO CORNER 15" Red Pine N 45 E marked S 36 NBT	14 Links
13"NPineS_51_E marked S l NBT	
	_60 Links

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as previously set by unknown surveyor. I' Iron Bolt in place. Corner lies in old fence corner to North and East.

County Road Commission records indicate this corner was in place in 1936.

Found no evidence of original B.T.'s.

Corner used by local residents for many years.

Corner was placed and witnessed 22 April 1958.

SURVEYORS SEAL

Billy B. Buckler DATE 4-15-59
REGISTERED LAND SURVEYOR