- MAY 2 2 1997 .

... ... u ne entre en 1/2 to

COMMISSION	LAND	CORNER RECOR	DATION CERTIFIC	CATE		
For corners in	Filin	g Requirement of A	ct 74, Mich. P.A. 1	970		
MARQUETTE				RECORDED	Dec.	26, 1996
(County)	Located In:	Corner Code #		AT ME 20		c P.M.
1. Dublin Land Com	سنا تخدم د سا			(3) tri	OF	PAGE
1. Public Land Survey	T <u>48N</u> R_ T <u>47N</u> R_		<u> 2.</u>		REGIST	ER OF DEEDS
	TR_		-			
2 Proporty Controlling			_			
2. Property Controlling in Section	S IR_ S TR_	· · · · · · · · · · · · · · · · · · ·				
3. Miscellaneous	S TR_		_		LBER	1 PAGE 37
Property in Sec.	S TR_		_	Register		amp & File Numb
	•					amp withoritania
4. Lot No, Record	led Plat	· .		A R C	D F F (
5. Private Claims	ı		***	1 T T	DEFG	
				2 6	5	3 2
ALAN K. PIERCE	in a field survey on	NOVEMBER 10 96 do	harabus etata that we do-	3		
Tarantinonia of 1 M. 14. Michigal	F.A. OLISTO, IDR COME	COUNTS PROPRIATION IN LINES	4 march 7 minutes success for	4 7 7	8 9	-10-11-1-1
United States Department of the Int	dies dieletore as required terior. Bureau of Land Ma	in the current manual of su	rvey instructions of the	5		
that the corner points mentioned in Board of Land Surveyors or by a	LIDES 3. 4 And 5 Above u	1979 in conformance with th	a milaa af iba tiilii	7	1 /	15141
recovered, found as expressed belo	w:	-carr, established, 16-6518	olisned, monumented,	8 - 19	2021	22 23 3
NOTE: Not more than 2 come	rs, all in the same town	and range may be recor	wlad	9		
on this certificate.		and range, may be recor	uou .		29 28	27 -26 -2
				11		
•				12 31 3	233	34353
Δ Description of original many				13		
A. Description of original mont		s and/or subsequent res	toration:			
Comer common to Sections 4,5,32 & 3	33, T47/48N - R30W					
1846; W. A. John & Austin Burt D. witnessed the original post with: 7" Spabove grade, with a cedar post "accord: 1-1/4" drill rod witnessed by P.K. nai L.4R.C., Pg. 401. 1984; Cothers by the same firm shows comers B. Description of corner evider	ing to the creek" witnessed ils in: 7" Maple N85*E 2 Corner shown on unrecord on the West side of I ake I	S46°E 46L. 1951: I by: 7" Basswood N55°E 2. 4.73'; 14" Basswood N60°I ad Certificate of Survey by	Per his personal field n 1'; 18" White Pine S12" 3 2.37'; 30" White Pine Clark/Minard Land Surv	otes, R.L.S. No. 4 W 22.8'. S10°W 22.95'; 4 veys, Job No. 84-	1348 set a 1-1/4 1984; L.L.S. " Maple S42"V	No. 30091 recovered V 17.32*. Recorded in
E-13: 1996; ECI recovered 1-1/4" drill rod. 1 G.L.O. 396' (call used to set corner in ECI 259' - G.L.O. 229' (indistinct) "to drill rod as a careful and faithful reestab	p ridge" ECI 1233' - G.L.	P ECL 223 - G.L.O. 304' () D. 1219': West "top ridge"	poorly defined margin), "	enter swamp" ECI	& G.L.O. 145	
•				0470		
				P.A. S	45,OF 1990	ER GROUP
		•			Carry)	Bussme
C. Description of monument for	corner and accessorie	s established to perpeta	uate locating the posi	tion of the Action	ar / //	14/96
1996: Replaced I-1/4" drill rod with a 2-3/8": 0.5' above grade. Bearing trees are face distances measured from a duplex nail with					ped to identify Three 1984 tre	the corner set about
·					المجتوب	OI BICE
Steel fence post with survey marker sign	uite Pine S15'W 23.23'; - North 1.2'.	6" Maple S45"W 17.32";	5" Maple N28°W 10	.10° (N.B.T.)	3251	100
4.51					<i>j</i> * [ALAN A
W /-					* ×	PIERCE
Signed by	· Wim			19-96	1×1	SURVEYOR /
Surveyor's Michigan License No.	30097				75	No. 30097
•					The state of the s	COLUMN SURVEY