SURVEY & REMONUMENTATION

JOB NUMBER: 94030 SHEET NO. : 1-462

in Section

Miscellaneous

Property in Sec.

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY HICHIGAN RECEIVED FOR RECORD

1994 DEC 28 PN 5:55

For corners in MARQUETTE Located In: Corner Code ## (County) T 48N R 25W 1. Public Land Survey ____ R __ T____R_ ____ T ____ R _ 2. Property Controlling

S ____ T ___ R __ S ___ T ___ R __

LIBER Register of Deeds Stamp & File Number

__ , Recorded Plat __ 5. Private Claims

, in a field survey on __Tuesday, December 20 , 19 ⁹⁴ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 12

A. Description of original monument and accessories and/or subsequent restoration:

I-2: Quarter Corner common to Sections 2 and 3. 1845: 1327.4'.

William Ives' original survey notes describe the corner monument as a wood post referenced by:

6" Y. Pine SO2W, 305 L On small lone ridge. No other tree convenient.

1892: The Plat of Island Beach Addition surveyed by George Lake Superior. (See reverse side after 1909 record).

1895: A survey by George P. Cummings indicates the East 1/4 Corner of Section 3 with a deflecting angle at the 1/4 Corner to the North of 1-15'. Distance South 2654.8', and Distance North of 330' to the Meander Corner on the shore of

P. Cummings indicates the West 1/4 Corner of Section 2 with 1909: The recorded plat of Presque Isle Addition surveyed by an angle on the East Side of the West Line of Section 2 at 'Charles Cummings indicates the 1/4 Corner and the Meander the 1/4 Corner of 181-13', and the Distance South listed as Corner North of there 330' North. No accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted the iron pipe as referenced in Part A above. The Distance South is 2653.64'.

RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Drove an 8.0' long 3/4" re-rod inside the found 1 3/4" iron pipe and capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

Tamarack S45E 37.37 ft. Carlson NBT

49.09 ft. Carlson NBT S30W

9# NOZE 94.23 ft. Carlson NBT Maple

N38E 98.00 ft. Carlson NBT

Steel sign post S05E 1.00 ft.

Monument is 0.3' above ground and is in an open marshy area.

Bk. 5, Pg. 123 and Bk. 7, Pg. 1

Merilda Contson Surveyor's Michigan License No.

__ Date 12-22

GERALD W CARLSON SURVEYOR No. 24589

OF MIC

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19

REVISED JAN., 19

Part "A" Continued:

1988: Gerald Carlson LLS No. 24589 found a 1 3/4" pipe in bog. Distance to SE Corner of Section 3 checked well to Cummings'survey. Set wood post along side iron pipe. Referenced by:

6" Tamarack
4" Tamarack
9" Maple
15" Red Pine 37.37 S45E, 49.11 S30W. N02W, 94.23 97.97 N32E.

L. 5 R.C., Pg. 151