SURVEY & REMONUMENTATION

JOB NUMBER: 94030

SHEET NO. : 1-454

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ē

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1991 DEC 28 PM 5: 55

ΓL	r corners in MARQUETTE CO	MMISSION Located In:	Corner Code ##	\mathcal{O}_{i}
	(County)	Located III.	Corner Code ====	Patricia d. Monles
1.	Public Land Survey	T R T R T R	1-8	REGISTER OF DESIRE
	Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R S T R		LIBER 1 PAGE 127 Register of Deeds Stamp & File Number
4.	Lot No,	Recorded Plat		A B C D'E F G H I J K
5.	Private Claims			A B C D E F G H I J K
				2 - 6 5 4 3 2
				3
1	GERALD W. CARLSON	Monday, No.	ovember 14 94	4 7 4 8 4 9 10 10 11
	nereby certify that under re	equirements of P.A. 74, Michigan P.A. o	f 1970, the corner points mention	, 5
in i	nes 1 and 2 above were	in conformance with regulations and	rules therefore as required in	the 16 17 16 15 14
Cur Ma	rent manual of survey inst nagement or by a decree o	tructions of the United States Departn f a Court of Law and/or that the corner	nent of the Interior, Bureau of La	
abo	ve were in conformance v	vith the rules of the Michigan Board of	Land Surveyors or by a Decree o	ola 19720727237
Col	irt of Law; established,	re-established, monumented, re-mo	onumented, recovered, found	as ⁹
•	ressed below:			10 30 29 28 27 26
NO	IE: Not more than 4 on this certificate	corners, all in the same town and	I range, may be recorded	11
	on this certificate	; ,		12 31 32 33 34 35
A.	Description of original	monument and accessories and/ommon to Sections 22 and 23. 1845	or subsequent restoration:	./4 Corner of Section 23 is shown on the
		l survey notes describe the corne		low's Addition # 5. Surveyed by G.F.
	monument as a 10" Asp		Cummings. No corner	
	10" Aspen N85E, 12	L	**	orner of Section 22 is shown on the
	1868: The West 1/4 Co.	rner of Section 23 is shown on th	recorded plat of Hom	estead Addition. No corner accessories
	recorded plat of Bald	win's Addition. No corner accesso	ries given. Surveyed by G	.P. Cummings.
	given.		(See reverse side).	
		of Section 23 is shown on the re's Addition # 1. No corner access		
в.	Description of corner (1994: Found and accept 2655.841.	evidence found and/or method ap ted iron as referenced in Part "A	plied in restoring or reestab " above. Distance South is	dishing corner: 2637.92' and Distance North is

RATIFIED BY PEER GROUP
P.A. 845 OF 1990

- Xarry & Bussne

Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1994 - Replaced 1/2* iron and cap #30091 with 3/4" x 8' long iron capped with a 3 1/4" diameter aluminum tablet
Marquette County Survey Monument stamped to identify the corner referenced by nails in:

Power Pole S87W 241.21 ft.

Power Pole N53W 332.02 ft.

Northmost Southwest corner of concrete foundation of house #623 N10E 107.68 ft.

Steel sign post N59E 2.64 ft.

Monument is 1.4' below ground and located on a sandy hillside roughly 150' South of Baraga Avenue.

Bk. 4, Pg. 146

Signed by	Gerold W Carlson	
•	24589	_
Surveyor's M	ichinan License No	

Date 12-22-94

GERALD W. CARLSON SURVEYOR No. 24589

OF MICH

IPOD AND SUBMETORS 31 28, 1971 UFELS 10 NEW SEPSIAY 14, 1975 SEPSED JAN., 1983

FORM APPROVED BY MICHIGAN STATE

Record No. 454

Part "A" Continued:

No date given: A county survey by George Cummings indicates the South 1/2 of the West Line of Section 23 as a distance of 2636'. The West half of the East-West 1/4 Line is a distance of 2647' and the North 1/2 mile of the West Line of Section 23 is 2647'.

1916: A county survey recorded by George Cummings indicates the East half of the East-West 1/4 Line of Section 22 a distance of 2572' and a distance on the North half mile of the East Section Line of Section 22 as 2647'.

1987: Charles Clark R.L.S. 25836 recorded a capped re-bar referenced by:

S.W. Corner House-Concrete Block Foundation	N10E,	107.70
Nail/Tag (R.L.S. 17618) in Power Pole	S86W,	241.40'
P.K. Nail in Street Light Pole	N55W.	331.96
Center of Sign (" Slow-Children") Post	N42W.	256.82
L.5 R.C., P. 104	,	200.02

1991: Certificate of Survey recorded by G. Carlson recorded in L.1, P. 670 indicates the East 1/4 Corner of Section 26. No corner accessories given.

1991: Certificate of Survey recorded by Glen Van Neste recorded in L. 001, P. 690 indicates the East 1/4 Corner of Section 22. Found cap with R.L.S. # 30091 referenced by:

Power Pole	S87W,	241.21'
Power Pole	N53W.	332.02
Power Pole	N31W,	112.82
Northmost S.W. Corner of Concrete foundation House # 623	N10E,	107.68

Joseph Charles