				F 5	20	
				13 G	RECE 1995	MARO
JOB NUMBER: 95053 PR 1598			*	2 W	5 =	8
SHEET NO. : 1-608	AND CORNER REC	ORDATION CERTIFIC	CATE	2 g.	RE IVE	<u> 36</u>
_ COMMISSION F	iling Requirement o	of Act 74, Mich. P.A.	1970	WESISTED OF THE PROPERTY OF TH	~ N □	오=
For corners in				≥ ₹	7	com
Located (County)	in:	Corner Code #		316	الله حد	25 25
				Mont		55
400	7 - 25W T			SS &	4 :)
	N R ^{25W} J-	9		00	7. 5.	, ~
	R	· · · · · · · · · · · · · · · · · · ·		1632 E	(C)	
	R					
	R					
	<u>R</u>					00
	R			LIBI	FR 1	L PAGE 28°
	R		Register o	of Deeds Sta		
Property in Section S T _	R					
A I IN December Olah						
4. Lot No, Recorded Plat				B C D E	F G H	I J K L
5. Private Claims				_65	43-	1-2-1-1-
			3			
•			4			
CUDATO II CADICON	Tuesday Versenh	- 7	4	-1-1-1-1	9-1-10-	
i, GERALD W. CARLSON , in a field survey of do hereby certify that under requirements of P.A.	on	er / , 19 ⁹⁵	5			
in lines 1 and 2 above were in conformance with re				~1817	-16	14-1-13-
manual of survey instructions of the United S				 		++++
Management or by a decree of a Court of Law an	d/or that the corner poin	its mentioned in lines 3, 4 a	and 8⊢	-1920	-21-22-	23 -24
5 above were in conformance with the rules of t	he Michigan Board of P	rofessional Surveyors or by	ya 🕍			 •
Decree of a Court of Law; established, re-established	hed, monumented, re-m	onumented, recovered, fou	ind 10-	-3029		2625-
as expressed below:			1.	<u> </u>	<u> </u>	
NOTE: Not more than 4 corners, all in the s	ame town and range, I	may be recorded	'			
on this certificate.			12	-3132	-33 -34-	35 36-
A. Description of original monument and	nananaariaa andlar a	sheaduant ractoration:	131			
•						
J-9: Quarter Corner common to Sections	23 and 26. 1846: Wil-	- in Record of Surveys	Pgs. 160 & 16	52 indicates	the Center	<u>-</u>
liam Ives' original survey notes descri	be the corner monu-	of Section to be an i	ron pipe and	that 5 addi	tional iron	1
ment as a wood post referenced by: pipes were set I			on the North	-South 1/4 L	ine ending	
6" Maple S23W, 28 l		with the North 1/16 C	Corner 1300' 1	North of the	Center of	
6" Maple N40E, 04 l		Section.				
1903: Charles Cummings'notes and maps o	f Section 26 record-	No Date: Recorded in	Record of Su	cveys Pgs. 1	58 & 159,	
ed in Record of Surveys Pgs. 160 & 161	indicates Section 26	George Cummings' (tra	nscribed) not	es indicate	Section 23	j.
to have been subdivided and the Center of Section to be to have been subdivided and t				outh 1/4 Cor	ner to be	
located at the intersection of the quarter lines. located 2648' East of the SW				er.		
1911: Charles Cummings'map & notes of S B. Description of corner evidence found a	ection 26 recorded	d in raetaring or recetab	diehina corna	.r.		
B. Description of corner evidence found a	mazor memoa appned	an restoring or reestab	maring corne	1-		
1995: Searched, and no subsequent evide	nce or corner found.	Distance West is 2652.	60', Distance	North is 5	244.04', an	ıd
Distance South is 5295.61'. This corner	was set at the inter	rsection of lines from	the N.W. Corr	er Section :	26 and thro	ough
a previously found 1/16 Corner (now des	troyed) in the inters	section of Adams and Ja	ckson St. ext	ended Easte	rly, and fr	:om
the South 1/4 Corner of Section 26 thro	-				erly. This	
position checks with Cummings surveys a	nd various recorded p	plats to the West and S	outh of the o	corner.		
				ED BY PEE	IR GROUP	
			P.A. 3	45 OF 1990	·~	
			Za	my y. K	Jussia	<u> </u>
			DATE	10/30	3/95	
	1	•	DATE.		/	
C. Description of monument for corner an	d accessories establi	shed to perpetuate loca	ating the posi	tion of the c	orner:	
1995: Set a 2 3/8" O.D. Aluminum Pipe w	ith a 3 1/4" diameter	aluminum tablet Marque	ette County S	Survey Monum	ent stamped	<u>.</u>
to identify the corner. Monument is 0.5			_	•	4	
4" W. Birch	N57E, 54.90'	. .	•		COLLE	w
19" Tw. Lombardi Poplar	S72W, 130.40'		1	4	ATE OF I	MCHIE D
12" Lombardi Poplar	S65W, 139.41'		4		See a service	- AND
C/L Top Bolt on Hydrant	N33W, 158.68'			<i>#</i>	GERALE	ע אי א נ א ע כ
Steel Sign Post w/Survey Marker Sign	North, 1.0'			<i>9</i> */	CARLS	
Bk. 11, pg. 63.	,			B*	SURVE	•
·				Ŭ-1	No.	,
				NS.		

Gereld W Carlson

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983