SURVEY & REMONUMENTATION

JOB NUMBER:			94030		
SHE	T	NO.	:	1-448	

Property in Sec.

Private Claims __

4. Lot No. _

expressed below:

*For corners in *

APR 28 1995

COMMISSION

___ , Recorded Plat ____

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN RECEIVED FOR RECORD

1994 DEC 28 PM 5: 54

Adrica REGISTER	_	
1500	1600	1 0
	4.7//	neter is
REGISTED	DC or m	~ 7 5

		WALLEYIENIENIE		
MARQUETTE		Located In:	Corner Code ≠#	
	(County)			
1.	Public Land Survey	T 47N R 25W	L-1 L-13	
		,		
		T R		
		T R	·	
2.	Property Controlling	S T R		
	in Section	S		
3.	Miscellaneous	S T R		

LIBER Register of Deeds Stamp & File Number

GERALD W. CARLSON	in a field survey on	Thursday,	December 22	, 19 ⁹ 4 ,
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru	uirements of P.A. 74, Mi conformance with reg	ichigan P.A. c julations and	of 1970, the corni I rules therefore	er points mentioned as required in the
Management or by a decree of a				
above were in conformance wit Court of Law; established, re	h the rules of the Michi- e-established, monum	gan Board of ented, re-m	Land Surveyors onumented, re-	s or by a Decree of a covered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

A. Description of original monument and accessories and/or subsequent restoration:

L-13: Quarter Corner common to Section 36, T48N-R25W and 1880: George P. Cummings survey indicates an iron at the Section 1, T47N-R25W. 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:

20" Hemlock N35E, 45 l

24" Hemlock N62W, 17 l

corner with the following distances noted: West, 2623.50 and East, 2623.50'. No corner accessories given.

1910: Charles Cummings survey indicates a Corner for commencing a survey in Section 1, T47N-R25W. No corner accessories given. (See Reverse Side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted DNR monument as referenced by G. Carlson in 1977. Distance West is 2623.41' and distance East to a calculated Township Corner in Lake Superior is 2632.61'.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Found Department of Natural Resources iron pipe with aluminum cap in place referenced by nails in:

7" Hemlock 11" Maple

S62E 23.31 ft. Carlson NBT

Maple'

S16W 8.24 ft. Carlson NBT

N23W 43.01 ft. Carlson NBT

Yellow Birch N20E 33.89 ft. Carlson NBT

South 1.35 ft. Steel sign post

Monument is stamped MCR 1994 on cap (Marquette County Remonumentation)

Bk. 5, Pg. 141

Surveyor's Michigan License No.

GERALD W CARLSON SURVEYOR No.

24589

Levald Warlse

_ Date