

Surveyor's Michigan License No.

32344

MARQUETTE COUNTY ENCHIGAN RECEIVED FOR RECORD

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1998 DEC 16 PM 3: 19

	Filing Requi	rement of Act 74, Mich. P.A.	1970
For corners in  MARQUETTE  (County)	Located In:	Corner Code #	Patricia a. Monley REGISTER OF DEEDS OF
1. Public Land Survey	T <u>48N</u> R <u>26W</u> T R T R		
2. Property Controlling in Section	S T R S T R		· <b>TD</b> 0 07
3. Miscellaneous Property in Sec.	S I R S T R		LIBER R2 PAGE 67
	<u> </u>		Register of Deeds Stamp & File Number
	ecorded Plat		
5. Private Claims			A B C D E F G H I J K L !
			2 - 6 - 5 - 4 - 3 - 2 - 1 -
		APRIL 28TH , 19 98 , d P.A. of 1970, the corner point	
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as			
required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points			
		h the rules of the Michigan Board of	of 6 18 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		ished, re-established, monumented	
recovered, found as expresse	J Delow:		8 19 20 21 22 23 24
	corners, all in the same town a	and range, may be recorded	10 30 29 28 27 26 25
on this certificate	i.		11
A. Description of original	monument and accessories an	nd/or subsequent restoration:	12 31 33 34 35 36
J-7: Quarter Corner comm		cribe the corner monument as a	13
wood post referenced by:	ii subdivision survey notes des	clibe the come mondifient as a	RATIFIED BY PEER GROOP
8" Sugar S50E,	12 L 8" Sug	ar N31W, 20 L	P.A. 345 OF 1990 Larry & Bresone
L.1, SM Pg. 192, and base	ed on a 1976 survey, indicates ction 23. Distance S02-20'-25 16.12' 24" W. I	"W, 1313.21" to the Center-No	DATE 12, 1998 Distance N89-31 -27"W, 1310.86' to the orth 1/16 Corner of Section 23. Referenced by:
1977: An LCRC recorded accessories found. He set Referenced by:	by William R. Donnan P.S. #17 a 5/8" X 36" rerod and cap m	'618 in L. 1, RC Pg. 203, indica idway on line between the N.W	ites no evidence of original monument or . Corner and the N.E. Corner of Section 23.
10" W. Pine S10E, 15" W. Pine S42E,		Pine N44E, 18.08'	
15 W. Fille 542E,	20.01		
J-7: 1996: Searched and the Donnan. Distances to reconchecked reasonably well. (1526' to summit. Checked summit. Checked Line Ca	found no evidence of original coorded references (L. 1, RC. Pg. Checked Line Call: (Summit of d Line Call: (Summit of knob, 2	203) checked reasonably well. knob of rock, 22.86 chains [15 29.84 chains [1969.44'] West for 7.58 chains [1160.28'] East from	shing corner: pted a 5/8" Rerod with Cap set by William R. Measurements to GLO Line Calls East and West 08.76'] West from corner); Measured Call: West rom corner); Measured Call: West 1950' to m corner); Measured Call: East 1119' to summit.
J-7: 1996: Replaced found	d 5/8" rerod and cap with a Se Monument stamped to identify		ing the position of the corner: upped with a 3 1/4" diameter aluminum tablet
17" W. Pine S37E,	, 28.85' (Donnan NBT)	13" W. Pine S0	05E,16.12' (Donnan NBT)
Established new reference 9" W. Pine S67W Survey Sign Post S21W	/, 37.48 <sup>'</sup>	•	orth, 39.32' orth, 14.9'
Note: Bearing trees have p	Yellow Survey Marker Sign painted face, butt, and side nai 5 and Corner Search Sheets 97	l blazes, d.h. measuring nails, a 1559	nd stamped B.T. Tigs affixed/IXTROM PROFESSIONAL SURVEYOR
SCA 97559			32344 32344
Signed by Lober	in O. Wietrow	) Nata /2	-15-98 POFESSIONAL

FORM APPROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995