APR 6 1 **1996** JOB NUMBER: 95053 LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 SHEET NO. : 1-653 For corners in Corner Code # Located In: MARQUETTE (County) R^{27W} T48N 1. Public Land Survey R^{26W} _ R Τ __ _T ____R_ 2. Property Controlling S ____ R in Section LIBER S ____ R 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section __, Recorded Plat_ 4. Lot No. Private Claims __ GERALD W. CARLSON Monday, December 11 _, in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

M-8: Quarter Corner common to Section 24, T48N-R27W and Section 19, T48N-R26W. 1844: Austin Burt's original survey notes describe the corner monument as a wood post referenced by:

10" Maple \$75W, 52 l

6" Sugar N57W, 30 1 No Date: The corner is shown on a field map for Northern

Lands and Timber recorded in L. 106, MR Pg. 720.

1966: The corner is shown on a road sketch to the Negaunee

1987: An LCRC recorded by Larry J. Bussone RLS #25833, in L. 5, RC Pg. 106, indicates no original evidence found. He set a 1" Iron at a point midway between the SW and NW Corners of Section 19, T48N-R26W. Corner hits just West of County Road. Established references:

8" Cherry S57W. 18.6

NO4E. 53.0' P. Pole C/L Road Due Éast, 22.5

7" Poplar N74E, 50.81

Rod and Gun Club recorded in L. 71, MR Pg. 452.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found and accepted a 1" diameter Re-bar, 0.32' above ground, on West side of North road. Re-bar cut with torch. Distance North is 2629.69' and Distance South is 2630.30'.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995; Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" aluminum tablet Marquette County Survey Monument over the top of existing 1" iron. Monument is 0.40' above ground, 22.5' West of C/L road, and stamped to identify the corner.

Established references using duplex nails set in: 4" Balsam

N36W, 18.131

N67W, 23.27' 5" W, Pine

18.93' (Bussone N.B.T.) S55W, 9" Cherry

S83E. 1.71 Green Steel Sign Post w/Survey Marker Sign N73W,

Note: Bearing trees were face and butt blazed, painted, and had B.T. Tags affixed.

Bk. 10, PP. 63-64.

Surveyor's Michigan License No._

Guold W Carlson

24589

GERALD W. CARLSON SURVEYOR No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975**