LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| MARQUE I | TE C | PTHUO |
|----------|------|--------|
| 1.10 | HiGA | ఓ |
| RECEIVED | FOR | Budost |

| MARQUETTE Located In: Corner Code # (County) 1. Public Land Survey T48N R27W A-01 A-01 T48N R28W M-01 M-01 | 1994 FEB 12 PM 3: 33 Partition of Amelogy REGISTER OF DEEDS OF |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| (County) 1. Public Land Survey T48N R27W A-01 T48N R28W M-01 | Particulate Manhous |
| T <u>48N</u> R <u>28W M-01</u> | property or prope Not |
| T49N R27W A-13 | REGISTER OF DEEDS DY |
| 749N R28W M-13 2. Property Controlling S T R | |
| 3. Miscellaneous STR | B 9 145 |
| in Section S T R | Register of Deeds Stamp & File Number |
| , topolity in odd. | register or beens oftening at he itemine. |
| 4. Lot No, Recorded Plat | |
| 5. Private Claims | A B C D E F G H I J K L M |
| | 2 - 6 - 5 - 4 - 3 - 2 - 1 - |
| • | 3 |
| I, George M. Platz , in a field survey on December 7 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in | 4 - 7 - 8 - 9 - 10 - 11 - 12 - |
| nereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current | 5 |
| manual of survey instructions of the United States Department of the Interior, Bureau of Land | 6 -18 -17 -16 -15 -14 -13 - |
| management of by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 | 7 |
| Court of Law; established, re-established, monumented, recovered, found as expressed below: | 8 19 20 21 22 23 24 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded | |
| on this certificate | 0 30 29 28 27 26 25 |
| | 11 |
| Township corner common to: Section 1 T.48N., R.28W. Section 6 T.48N., R.27W. | 12 31 32 33 34 35 36 |
| Section 31 T.49N., R.27W. Section 36 T.49N., R.28W. | 3 |
| • | RATIFIED BY PEER GROUP |
| A. Description of original monument and accessories and/or subsequent restoration: | P.A. 345 OF 1990 |
| 1846: Original U.S. Government Survey by Austin Burt - Set wood post witnessed by N56°E 10 Links; 8" Spruce | : Lamy flacosme |
| N68°W 13 Links; 6" Spruce | DATE 12/7/98 |
| 1916 -1918: Section corner coordinate information from Cleveland Cliffs Iron Compa"standard" brass capped monument. No additional information given. | any indicates the corner to be a |
| 1981: L.C.R.C. recorded in L.4 of R.C., P.150, Marquette County Records. Robert diameter x 4' long galvanized iron pipe and brass cap stamped with appropriate stamped "Mead", "RLS 8317" and "1981" on the cap. Witnessed by: N51°E 11.4'; & of 8" Black Spruce S51°E 15.8'; & of 6" Black Spruce West 10.8'; & of 8" Black Spruce N37°W 13.0'; & of 6" Black Spruce | Schmeling, PS 8317 found 1-1/2" riate corner identification. |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing con | ner: |
| Found 1 1/2" diameter galvanized iron pipe with brass cap 24"+/- above ground, stass described in L.C.R.C. recorded in L.4 of R.C., P.150 Marquette County Records. Spruce B.T. located N56°E; 10 links. A thorough search found no evidence of any occupation in the immediate area. The position of the corner has been used and acmarkings. Original GLO line calls are not distinct enough to verify the position obtainable recorded survey information and any other obtained unrecorded survey in Debecker Associates is documented in the research dossier. Considering the above the correctness of this point. | amped with appropriate identification Found possible remains of original 8 other survey monumentation or ccepted by others as evidenced by line of this point. All measurements, nformation made available to Snalding |
| C. Description of monument for corner and accessories established to perpetuate locating the pos | sition of the corner: |
| Accepted found 1 1/2" diameter galvanized iron pipe and brass cap stamped with appunder 1998," on brass cap to properly identify accepted corner. Made the following | propriate identification. Stamped g witnesses: |
| Az. 37° 11.90' Set mag nail w/tag No.38121 in N.W. face of 12" Black Spruce with Az. 164° 10.25' Set mag nail w/tag No.38121 in W. face of 4" Black Spruce Az. 299° 16.84' Set mag nail w/tag No.38121 in S. face of 7" Black Spruce Az. 334° 10.30' Set mag nail w/tag No.38121 in N.E. face of 10" Black Spruce | B.T. tag affixed B.T. tag affixed Control of Michigan Control of |
| | GEORGEM. |
| Signed by George M. Clitz D | ate 12-30-98 No. |
| Signed by George M. Clatz Da | GEORGE M. * GEORGE M. * GEORGE M. * PLATZ SURVEYOR SOLUTION |