## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	MARQUETTE CO.
1. PUBLIC LAND SURVEY	T. 50 N. R. 28 E.		20.
2. PROPERTY CONTROLL- ING IN SECTION———	,T N. E. W.		,
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed below as of survey instructions of the U court of law. Furthermore,  formance with the rules of the law:  A. Description of original mon West 4 corner. Origin 10 lks. D. Delamater -	lines 1 and 2 above (iden 19.77, established and in conformance with regu- nited States Department of that the corner points may found, recovered, restored, e Michigan State Board of R ument and accessories and/ al - wood post - sugg	tified with circles on index, re-established, monument lations and rules therefore the Interior, Bureau of Landentioned in lines 3,4 and 5 stablished or re-established egistration for Land Survey or subsequent restoration:  ar 14 - N34 W - 33 14 - 12" hem N15 W -	P.A. 74, Michigan P.A. of 1970, a code diagram — over) were, in a ted, re-monumented, recovered or as required in the current manual distancement or by a decree of a babove were, in a field survey on dissexpressed below and in contors or, by a Decree of a Court of the contors
B. Description of corner evide Found cabin spike set b place and in good condi original witness.	y D. Delamater about	1953. Both of Delar	mater's witnesses in
B. Description of corner evide Found cabin spike set b place and in good condi	y D. Delamater about	1953. Both of Delar	mater's witnesses in
B. Description of corner evide Found cabin spike set b place and in good condi	y D. Delamater about	1953. Both of Delar	mater's witnesses in
B. Description of corner evide Found cabin spike set b place and in good condi original witness.	y D. Delamater about tion except blazes w	1953. Both of Delar are grown over. Set	nater's witnesses in by Delamater from
B. Description of corner evide Found cabin spike set b place and in good condi original witness.	y D. Delamater about tion except blazes we for corner and accessories p buried in centerli N12°W - 27.6'; 20" H	established to perpetuate lone of road.  Maple - S35 W - 20	nater's witnesses in by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum cauding of N.B.T.s 18" hem. = 16" hem. = \$120E = 29.7"	for corner and accessories  buried in centerli  12°W - 27.6'; 20" H  18" hem N72°E -	established to perpetuate lone of road.  Maple - S35 W - 20	nater's witnesses in by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum cauding of N.B.T.s 18" hem. = 16" hem. = \$120E = 29.7"	for corner and accessories to buried in centerli N12°W - 27.6'; 20" H; 18" hem N72°E - (NEW)	established to perpetuate lone of road. Maple - S35 W - 20 61.3'	nater's witnesses in by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum cape old N.B.T.s 18" hem. = 16" hem S12°E = 29.7" (NEW)  SIGNED BY.  SURVEYOR'S MICHIGAN RE	for corner and accessories to buried in centerling we will be a solution of the solution of th	established to perpetuate lene of road.  Maple - S35 W - 20 61.3'	nater's witnesses in by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum ce Old N.B.T.s 18" hem. = 16" hem S12°E = 29.7" (NEW)  SIGNED BY.	for corner and accessories to buried in centerli N12°W - 27.6'; 20" H; 18" hem N72°E - (NEW)	established to perpetuate lene of road.  Maple - S35 W - 20 61.3'	by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum ca Old N.B.T.s 18" hem 16" hem \$12°E - 29.7" (NEW)  SIGNED BY	for corner and accessories to buried in centerli N12°W - 27.6'; 20" H; 18" hem N72°E - (NEW)	established to perpetuate lene of road.  Maple - S35 W - 20 61.3'	by Delamater from ocating the position of the corner:
B. Description of corner evide Found cabin spike set by place and in good conditioning original witness.  C. Description of monument 1" pipe, 4" aluminum ca Old N.B.T.s 18" hem 16" hem \$12°E - 29.7"	for corner and accessories to buried in centerli N12°W - 27.6'; 20" H; 18" hem N72°E - (NEW)	established to perpetuate lone of road. Maple - S35 W - 20 61.3'	nater's witnesses in by Delamater from

Form No. All A1736

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28. 1371. DISTRIBUTED BY MICHIGAN ROCIFTY OF REGISTERED LANG STATE OF