## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 34 NR 25 W.

	Menominee COUNTY
DESCRIPTION OF CORNER	1/4 Corner between Sec. 's 4-9
DESCRIPTION OF CORNER I	MONUMENT_1" pipe with 4" b rass cap
WITNESSES TO CORNER _	26" elm clump N 78° E 48 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner. Found two old wood posts on south edge of stone fence. Probable cedar B.T. laying down on stone fence.

Distance checks good east to meander corner and west to Section Corner.

SURVEYORS SEAL

SIGNED SILLY SURVEYOR DATE 5/10/57