STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		<u>35</u> T <u>34</u> n R' <u>s 25 & 2</u> 6
DESCRIPTION OF CORNER _		T35N R26 W 36/31 T35N R25W R Town corner for sections T34N R26W 1/6 T34N R25W
CORNER MONUMENT		1" iron pipe with 4" aluminum cap
DATE	MONUMENT PLACED	AND WITNESSED 4/15/70, F. J. Bray
WITNE:	SSES TO CORNER.	8" Cedar (S.36) (NBT) N 03° W, 56.0'
N°	6	7" Cedar (S.31) (NBT) N 66° E, 43.3'
	T 3 4 N R 2 5 W	12" Tamarack stub (NBT) S 02° E, 13.9' AND
CIF	CLE CORNER REGI	STERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two wood posts. Found rotted tamarack stump bottoms in proper bearings and distances from posts. These rotted stump bottoms could be possible original B.T.'s. Ridge to the north checks well with original notes.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

ED Frank J. Broy DATE 6/25/70

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68

COUNTY

W

Menominee