

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

| | | |
|---|---------------------------|------------------------|
| <u>Menominee</u> <small>(County)</small> | Located In: | Corner Code <u>C-2</u> |
| 1. Public Land Survey | T <u>34N</u> R <u>25W</u> | |
| | T _____ R _____ | |
| | T _____ R _____ | |
| | T _____ R _____ | |
| 2. Property Controlling in Section | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2 | 6 | 5 | 4 | 3 | 2 | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, David Babbitt, in a field survey on 1/27, 1987, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- C-2. East 1/4 corner of Section 6. Set DNR Monument. 8/2/82.
 6" r.maple, S16W, 29.6'
 10" w.birch, N53W, 14.3'
 16" r.maple, S54E, 28.0'
 5" r.maple, N63E, 46.2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- C-2. On 5/2/83 two of the above NBT's were found to have been destroyed by road construction. The following two NBT's were marked at that time to replace those destroyed.
 15" r.maple, S81E, 37.9
 9" w.birch, S41W, 21.8

In 1986, it was discovered that additional NBT's had been cut by loggers. Marked new NBT's 1/27/87 to replace those cut. Present NBT's are as indicated in part "c".

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-2. DNR Monument.
 1982 wit. 10" w.birch, N53W, 14.3
 1983 wit. 9" w.birch, S41W, 21.8
 1987 wit. 4" w.birch, S28W, 6.4
 1987 wit. 8" r.maple, N39W, 43.7

Signed by David B. Babbitt Date 1-28-87
 Surveyor's Michigan License No. RLS 21558