## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_34\_ NR\_26\_W \_\_

			Menominee	COUNT
DESCRIPTION (	OF CORNER	1/4 Section (	Corner_between Sect	ions <u>13</u> and 14
DESCRIPTION C	F CORNER	MONUMENT	lm pipe with 4" br	ass_cap
WITTNESSES T	TO CORNER	9" Cedar	_ s_41° W	86_links
		7" Hemlock	_ N 23° M	24 links
	•			
			<b></b> .	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set 1/4 Corner, this 1/4 corner has been set about 25 years ago. Old Cedar stake in place. One Hemlock tree in proper position. Very old chopping but nothing to identify (possible B.T.).

Distance North checks to swp. edges and 1/2 mile North to road intersection.

Corner placed and witnessed May 8, 1956.

SURVEYORS SEAL

SIGNED Silly D. Suesles. DATE 5/14/56