## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
	1. PUBLIC LAND SURVEY	N. S., R E.		
	2. PROPERTY CONTROLL- 24 ING IN SECTION—	,T. 34 N. R. 26 E	1, 2, 10, 14	
	3. MISCELLANEOUS PROPERTY IN SECTION.	,T N. E E		
	4. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS	······································		REGISTER OF DEEDS STAMP AND FILING NUMBER
	the corner points mentioned in field survey on December restored as expressed below an of survey instructions of the Uncourt of law. Furthermore,	lines 1 and 2 above (ide 11 1980, established in conformance with regulated States Department of that the corner points of found, recovered, restored,	entified with circles on indeped, re-established, monument gulations and rules therefore a f the Interior, Bureau of Land mentioned in lines 3,4 and 5 established or re-established	P.A. 74, Michigan P.A. of 1970, a code diagram – over) were, in a ed, re-monumented, recovered or as required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in control or, by a Decree of a Court of
1	A. Description of original monument and accessories and/or subsequent restoration: West 1/16 on North section line; not previously established.			
2	East 1/16 corner on the north section line - Section 24; not previously established.			
10	South 1/16 on west section line.			
14	South 1/16 corner on the east section line of Section 24; not previously established.			
1	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the N. 1/4 corner and the N.W. section corner of Section 24.			
2	Set M.P.O.L. between the N. 1/4 corner and the N.E. section corner of Section 24.			
10	Set M.P.O.L. between the W. 1/4 corner and the S.W. section corner of Section 24.			
14	Set M.P.O.L. between the E. 1/4 corner and the S.E. section corner of Section 24.			
ALL 1	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  - 1" pipe, 4" aluminum cap.  6" R. Maple - S35°E - 9.7'; 14" R. Maple - S61°W - 23.8'; 8" Twin W. Birch - N45°W - 7.8'  6" R. Maple - N62°E - 10.7'.			
2	9" Cedar - N12°E - 20.4'; 9" Cedar - S18°W - 39.1'; 9" Cedar - S49°W - 39.1'; 4" B. Ash - N85°W - 15.2'.			
10	5" R. Maple - S15°W - 7.7'; 4" B. Ash - N24°W - 5.3'; 9" R. Maple - N54°E - 17.0'; 5" R. Maple - S64°E - 18.8'.			
14	9" Cedar - N83°E - 12.7 10" Cedar - N17°W - 29. SIGNED BY	'; 4" Cedar - N82°k 05'.	/ - 28.45'; 5" Cedar -	N66°W- 22.15';
	SURVEYOR'S MICHIGAN REG			(SEAL)
	FOR STATE AND UNITED STATES AGENCIES:			
	SIGNED BY DATEDATE			
	APPROVED AND SIGNED BY_	$\langle II \rangle \cdot \rho \cdot$	AND SURVEYOR DATE	1-26-81
				(SEAL)

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

14

Form No. ML M735 DOUBLE DAY BROS. 6 CO., KALAMAZOO, MICH.