REMONUMENTATION

FEB 1 1 1998

Land Survey Remonumen Peer Group Under Act 345 Of P.A. Of 1990 Oc. 199. SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in **MENOMINEE** Located In: Corner Code # I-08 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 5. Private Claims , 19 ⁹⁷ William Lenca Nov. 03 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original Survey by James H. Mullett - B.T.'s - W. Pine, 18" - N18°W - 20 lks.; W. Pine, 10" - S60°E - 08 lks. All original evidence for this corner has been destroyed by railroad construction and by county road improvements. 1900: Survey by Albert Hass states "Set "T" rail 3' long which is 39 lks west of the west rail of the C&NW RR Co's Track. L.C.R.C. No. 169 by George B. Wilson states, "Found old iron pin, checks well with survey by Albert Hass in the year 1977: 1900." 1/2" dia, iron pin - 28.38' west of the centerline of the rails - tied into certified survey No. 75. Certified Survey No. 794 by William Lenca, RLS 26461, shows this corner as being 2604.43' south of the N.E. Corner of 1993 Section 22, T34N - R27W. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a P.K. nail set over a very old 1/2 inch diameter iron in location as described in L.C.R.C. No. 169. Corner falls 2' north of present county road centerline and 26.0' west of the west rail of the present Chicago and Northwestern Railroad. This fits very closely with Albert Hass's record measurement of 39 links (25.74 feet). This position has been used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner. DE MICHIC WE HAM LAND SUZVEY OF C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. STATE INDIVIDUAL Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: Southwest Bolt on base of Railroad Signal N680E 44.14 fect Southwest Bolt on base of Railroad Signal S390E 25.25 feet 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 2' N. of Power Pole S450W 36.49 feet 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 2.2' N. of C.R. Sign N580W 42.71 feet Metal Survey Sign Post NI40W 36.0 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Nov. 04, 1997

Approved by Menominee County

Surveyor's Michigan License No.