## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_35\_ NR\_\_25\_W\_

		_ Menominee	COUNTY
DESCRIPTION OF CORNER	1 _ 1/4 Section Corne	er_between_Sections_1	4 and 15
DESCRIPTION OF CORNER	MONUMENT1" J	oipe with 4" brass ca	P
WITNESSES TO CORNER	7" Cedar	N_13°_W	$72\frac{1}{2}$ links
	6" Cedar	N_86°_E	_62 _links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners.

No evidence of original 1/4 Corner.

Corner lies in wet swamp.

Corner placed and witnessed July 12, 1956.

SURVEYORS SEAL