MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_35_ NR 25 W___

	Meŭoŭiŭeē COUNT
DESCRIPTION OF CORNER	Section Corner common to Sections 11, 12, 13, 14
DESCRIPTION OF CORNER	MONUMENT 1" pipe with 4" brass cap
WITTNESSES TO CORNER	9" Cedar N 1° W 50 links
	8" Cedar S 19° E 32 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from two Cedar B.T.'s, poor condition.

Concrete monument in place set by unknown persons.

Corner found by Forestry Division Survey Crew while making a partial re-survey of this township.

Corner placed and witnessed March 15, 1956.

SURVEYORS SEAL

SIGNED SIELLY Suckles DATE 3/19/56