## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 35 NR 25 W ...

				Me	nominee		COUNT	Υ
DESCRIPTION	OF	CORNER	Section Corne	er common i	to <u>Sectio</u> n	s 16, 17,	20, 21_	
DESCRIPTION	OF	CORNER	MONUMENT	l" pipe w	i <u>th</u> 4" _b <u>r</u> a	es cap		
WIT TNESSES	то	CORNER	5" W. Ash	]	N 600 M	12	links	
			5"_W. Ash		<u>N 62° E</u>	<u>- 11</u>	_links	
				. <b>-</b>	<del>-</del> -			
					<del>-</del> - <del>-</del>			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Established Section Corner.

Swamp edges North and East check very good.

Distance checks to Section Corner one mile West and Proportionate Measure N. and S. ok.

Hemlock stp. (badly rotted) and possible Cedar stp. bottom in proper place.

Corner placed and witnessed May 21, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 5/23/56 \_