## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_35\_ NR\_25 W\_\_

		M	enominee	COUNTY
DESCRIPTION OF CO	RNER Section	Corner common	to Sections 15.	16, 21, 22
DESCRIPTION OF COP	RNER MONUMEN	Tl"_pipe_wi	ith 4" brass cap	
WITTNESSES TO COL	RNER 6" Sof	t Maple	N 500 M	33 links
	10"_ Whi	te_Birch	<u>s 60° W </u>	_1 <u>1</u> 3_1 <u>i</u> nks
		<del>.</del> .	<b></b>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from two Hemlock stps. badly rotted and burned, (probable B.T.'s) in proper position.

Distance checks South 1 ch. to swp. and East 9 chs. to swp. North to Stream.

Corner placed and witnessed May 22, 1956.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 5/23/56 -