## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_35\_ NR\_25\_W\_\_

	Menomines COUNTY
DESCRIPTION OF CORNER	Section Corner common to Sections 17, 18, 19, 20
DESCRIPTION OF CORNER	MONUMENT_l"_pipe_with_4" brass_cap
WITTNESSES TO CORNER	34" White Pine Stp. N 72° W 34 links
	24" White Pine Stp. N 74° E 52½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner from two probable Hemlock stp. bottoms in proper position.

Traces of two stakes in soil. Distance checks to swp. and stream West; and to swp. and stream South.

Corner lies 1.88 chs. W. and 1.33 chs. S. of 80.00 ch. marker from North.

Corner placed and witnessed April 19, 1956.

SURVEYORS SEAL

SIGNED Silly D. Buckey DATE 5/14/56 \_\_\_\_\_ DATE 5/14/56\_