Approved by Menominee County
Land Survey Remonumentation
Page Group Under Act 345 Of

Peer Group Under Act 345 Of
P.A. 01 1990 On DEC 20 199 5
a) alian Frus
W/WWW/ June

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Menominee	Located In:	Corner Code ##	PAGE PAGE
(County)  1. Public Land Survey	T <u>36N</u> R <u>25N</u> T <u>36N</u> R <u>25N</u> T R	113 (X1 T35NESSM)	JAN -3 JA STATE OF SERVICE OF SE
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R  S T R  S T R  S T R  S T R	,	Register of Deeds Stamp & File Number
I. Paul R. Bressette do hereby certify that under red in lines 1 and 2 above were in current manual of survey instruments of by a decree of	, in a field survey on <u>J13 Ma</u> quirements of P.A. 74, Michigan P.A n conformance with regulations a uctions of the United States Depa a Court of Law and/or that the corn	y 08, 1995 y 03, 1995 A of 1970, the corner points mentioned in the interior, Bureau of Land ter points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a	2 6 5 4 3 2 1 1 2 2 2 3 24
Court of Law; established, expressed below:	re-established, monumented, re- corners, all in the same town a	-monumented, recovered, found as	
A. Description of original	monument and accessories an	nd/or subsequent restoration:	

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J13) Found Buckler's monument and witnesses as described. Y. 8irch NBT is alive and standing N19E 31.9' from monument with both faces completely closed. Cedar NBT is alive and standing with faces open and scribing plain. Monument was rewitnessed as found and is accepted as a careful and faithful PERPETUATION of the position of the original corner. A new witness was marked to replace the Y. 8irch due to the faces being closed and the advanced age of the tree.

(J13) Quarter corner common to Sections 35 and 2. 1848: James H. Mullett, DS. Set wood post witnessed by: Birch 14 N73E 16 lks.; Cedar 14 N17W 30 lks. 1955: Billy Buckler, RLS. Set 1" iron pipe with 4" brass cap from original Y. Birch BT and cedar stump bottom in position for second original BT witnessed by: 14" Y. Birch N15E 48 lks.; 9" Cedar S57W 32 lks. Corner recorded in Volume 2 p.

(K13) Section corner common to Sections 35, 36, 1 and 2. 1848: James H. Mullett, DS. Set wood post witnessed by: Cedar 6 N38W 10 lks.; Spruce 10 N52E 14 lks. 1848: James H. Mullett, DS. Closed on corner during subdivision of T35N, R25W. Marked two additional

- (K13) No evidence of original survey or restoration found. Corner position re-established mid-point and on-line between the South Quarter corner of Section 35 and the South Quarter corner of Section 36, and is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J13) 1" iron pipe w/ 4" brass cap Hemlock NOTE 21.75' (1/4S,NBT) (1/4S, NBT) R. Maple S21E 7.65 11" Cedar S61W 21.3' old NBT 10 Ash N35W 28.8 (1/4S, NBT) All NBT's are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are measured to notch in butt blaze, bearings are magnetic.

55 of Menominee County Records.

witnesses: Spruce 12 S38W 11 lks.: Spruce 12 S26E 17 lks.

(K13) 1" iron pipe w/ 4" aluminum cap 8" Cedar N31E 12.3' (S36,N8T) 8" Cedar S54E 34.25' (S1,NBT) 6" Cedar S05M 20.7' (S2,NBT) 8" Cedar N82M 25.15' (S35,NBT) All NBT's are blazed, scribed, painted and tagged. A metal post with sign was placed next to monument. Distances are measured to notch in butt blaze, bearings are magnetic.



Signed by	Taul R. Trimite
- J · · /	プフココム

Date 1-3-96

Surveyor's Michigan License No. 37270

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971