SURVEY & REMONUMENTATION

JAN 092001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Approved	by Menominee County
	vey Remonumentation
Peer Gro	oup Under Act 345 of

Peer Group Under Act 345 of
P.A. Of 1990 On 1/1/3, 20/20
Peer Group Under Act 345 of PA. Of 1990 On 2000

For corners in	Filin	Filing Requirement of Act 74, Mich. P.A. 1970 Chairman				
MENOMINEE	Located In:	Corner Code #		Boo	e 1	7
(County)		- some ocac "		م م	~ 6	Page (1)
1. Public Land Survey	T_35NR_ TR_ TR_	26W K-1	- -) FOR RECORD 10 10:16:09 A
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_		- - - -	Registe	BARBAR REGISTE MENOMINE	A MORRISON R OF DEEDS E. MI 49858 tamp & File Number
4. Lot No, Reco	rded Plat			·		
5. Private Claims SAME AS CORNER K-				1 A B C 2 6 -	D E F (3 H I J K L
William Lenca	in a field augustus.	Jul 00		3		
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	an P.A. of 1970, the corner I rules therefore as required Interior, Bureau of Land Ma in lines 3, 4 and 5 above we a Decree of a Court of	I in the current manual of sur inagement or by a decree of a vere in conformance with the	and 2 above were vey instructions of the Court of Law and A	in 5 18 or 6 18	-17 -16 -20 -21	-10 -11 -12 -15 -14 -13 -22 -23 -26
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.		ed	9	29 28	27 26 25	
				11 12 31	-3233	34 35 36-
A. Description of original mor	nument and accessories	s and/or subsequent rest	oration:	131		
improvements. 1986: L.C.R.C. No. 740 marked MENOM West." TIES: c/), Book 3, by William I IINEE COUNTY SUR	B.T.'s - Cedar, 12" - N6 20 lks. All original evid Lenca, RLS No, 26461 EVEY MARKER in line 42.71'; c/l Power Pole, 60.23'.	ence for this constates "Set 30" lo	mer has been de:	stroyed by Co	ounty Road
B. Description of corner evid	ence found and/or meth	nod applied in restoring o	r reestablishing c	orner		
We found a W-1-B Bernts described in LCRC No. 74 county roads running Nort available evidence for the	en Monument with the 60 - Book 3 (see part A th - South - East and W	e top sheared off by cour), and found it to be in t Vest, has been accepted	ity snow plow.	We verified its p	falls in the ce is accepted a	. 11 0
C. Description of monument for	or corner and accessorie	es established to perpetu:	ate locating the p	osition of the cor		90461
Set 5/8" x 24" Iron Rod/3-	1/4" dia. Alum. cap sta	amped for corner location	n in Monument	Box:	SALES IF R	FO LAND SURFACE
6" dia. Elm 12" dia. Cedar 6" dia. Cedar 5/8" x 24" Iron Rod/2" Metal Survey Sign Post	dia. Alum. cap markec		N45 ⁰ E \$37 ⁰ E \$43 ⁰ W	79.35 feet 82.86 feet 96.48 feet 35.74 feet 36.4 feet	Scr. NBT Scr. NBT Scr. NBT @ Survey	Sign Post
NOTE: All bearings are m	agnetic bearings. All	distances are measured	with steel tape.	Distances to tree	es are to nail	in side of tree.
Signed by (1) Clism	Fina			Aug. 8, 2000		
Surveyor's Michigan License No	26461					