OCT 9 7 1999

200	20 miles 1	A 50 A 54
- L	7 4 11 11	MAL

Approved by Menominee County Land Survey Remonumentation

SECTION					Peer Group Under Act	345 Of
		• • •	ATION CERTIFIC		My Dayi	P1 C
For corners in	Filing Req	juirement of Ac	t 74, Mich. P.A. 19	170	Chalman	/
MENOMINEE	t to d for	Codo #		- !	#22 9	i i
(County)	Located in:	Corner Code #				KECEIVEO FOR
1. Public Land Survey	T <u>35N</u> R <u>27W</u>	C-3	No.	1	記とこ	Ĝ
1. Public Latid Survey	TR			!	14 Sept.	
	TR		-	-	開発を開始	A T T
2. Property Controlling	S TR		<u> </u>	4	88888 € = =	<u> </u>
in Section	S TR		_		<u> </u>	
3. Miscellaneous Property in Sec.	S IR S T R		_	5	/ D d. Ot	Film Mounds on
, , , , , , , , , , , , , , , , , , , ,				Kegister c	of Deeds Stamp &	File Number
4. Lot No, Record	led Plat					
5. Private Claims	700 Fide			A B C I	DEFGH	I J K L N
		•		2 6	5	
	7.1	20		3		
ı, William Lenca, requirements of P.A. 74, Michigan	in a field survey on <u>July</u> PA of 1970, the corner point	1999 do	hereby state that under 1 and 2 above were in	4 - 7 - 1 -	8	11-1-12-
conformance with regulations and r	rules therefore as required in the	current manual of su	urvey instructions of the	5		
United States Department of the Inthat the corner points mentioned	in lines 3, 4 and 5 above were in	conformance with th	ne rules of the Michigan	6 19 7	\\ \	14-1-13
Board of Land Surveyors or by recovered, found as expressed belonger	a Decree of a Court of Law;	established, re-esta	ablished, monumented,	8 19	20-21-22-	23 24
,	•		-4-4	9		
NOTE: Not more than 2 come on this certificate.	ers, all in the same town and r	ange, may be reco	raea	1030		2625-
Oil Bild Columbia				11		
				12 31 3	33 34	35 36
	•			13		
A. Description of original mor	nument and accessories and	l/or subsequent re	estoration:		•	
1848: Original Survey	by James H. Mullett - B.T.	's - Black Ash, 6'	- N43 ^o W - 12 lks;	Cedar, 10" - S3	5 ⁰ E - 25 lks. All	loriginal
evidence for this	corner has been destroyed	by county road in	mprovements.			
B. Description of corner evid	ience found and/or method	applied in restoring	g or reestablishing co	rner:		
,	re-established in the center				West. This positi	on fits well
with existing lines of occi	upation and with measuren	nents to corners 1	1/2 mile North, 1/2 n	nile South, 1/2	mile East and 1 n	nile West,
and is accepted as the bes	st available evidence of the	position of the or	riginal corner.			
					THE TAXABLE PARTY.	M. Elean
C. Description of monument f	for corner and accessories e	stablished to perp	etuate locating the p	osition of the cor	ner:	
Set 2" dia. Aluminum Pi	pe 30" long/3-1/4" dia. Alu	ım cap stamped f	or corner location:		* * * * * * * * * * * * * * * * * * *	relian * * *
TT	oh NGZOD	76 24 fact	Cor NIDT		Trans.	LAND
Twin 6" dia. White A 5" dia. White Ash	Ash N76 ^O E S44 ^O E.	76.34 feet 49.09 feet	Scr. NBT Scr. NBT			Mo.
6" dia. Elm	N550W		Scr. NBT			2646
Acusto . O' B	ort geoffst	25 60 E			New Trans	D 1830
Metal Survey Sign Po	ost S52°W	35.69 feet				annot.
NOTE: All bearings are	magnetic bearings. All di	stances are measi	ared with steel tape.	Distances to tre	ees are to nail in	side of tree.
Signed by // Clare	n Harris		Date	Sep. 7, 1999		<u> </u>
Surveyor's Michigan License	' y '					
		·				