MAR 29 2000

MAR & 3 ZUUU	PA Of 1990 On 10/1 199 2
SECTION LAND CORNER RECORDATION OF Filling Requirement of Act 74 Mind	
For corners in Filing Requirement of Act 74, Micl	h. P.A. 1970 GRAITIBAT
MENOMINEE Located In: Corner Code #	BK 6 P8. 97
(County)	RECEIVED FOR RECORD
1. Public Land Survey T_35NR 27W E-01	28 DEC 1999 3:56:09 PM
TR	BARBARA MORRISON
TR TR	REGISTER OF DEEDS MENOMINEE, MI 49858
2. Property Controlling S T R	F 11510111455 111 43858
in Section S T R 3. Miscellaneous S T R	
Property in Sec. S T R	Desirber of Desire Control of
	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	A B C D F G H I J K L
(SAME AS CORNER E-13 T36N - R27W)	2 - 6 - 5 - 4 - 3 - 2 - 1
t, William Lenca , in a field survey on Oct. 1999 do hereby state	that under
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above	ve were in
conformance with regulations and rules therefore as required in the current manual of survey instructi United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Land	awand for class and and are
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, mor	Michigan
recovered, found as expressed below:	8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11 12 13 13 13 14 17 14
•	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original monument and accessories and/or subsequent restoration:	
 Original Survey by John Mullett - B.T.'s - Hemlock, 20" - N43°E - 47 I evidence for this corner has been destroyed by County Road improveme Sectional Subdivision by James H. Mullett - B.T.'s - Birch, 12" - \$80°W original evidence for this corner has been destroyed County Road improvement Plat of Survey by Justus Little recorded in Record of Surveys book in Retorn to other corners in Section 4, T35N-R27W. One tie is shown - "Cedar I 	onts. V - 34 lks.; Hemlock, 16" - S37°E - 24 lks. All overnents. egister of Deeds Office shows this corner as it relates
B. Description of corner evidence found and/or method applied in restoring or reestable	•
Due to county road improvements over the years, we were unable to recover evid We accepted the centerline of a 3 way couty road intersection (roads run East - W from this location to corners 1/2 mile West (2691.06 feet), 1/2 mile East (2685.4 reasonably well. The GLO record to the corner 1/2 mile South is 2544.3 feet. W road centerlines as the best available evidence of the position of the original corn	Vest - South) for this corner position. Measurements 2 feet) and 1/2 mile South (2543.12 feet) fit //e therefore accepted the intersection of the county
C. Description of monument for corner and accessories established to perpetuate locating	ng the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Mo	nument Box:
	52° E 46.52 feet 1 ft. E of power pole
D-1	50 E 64.33 feet Scr. NBT 50 W 43.06 feet
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" N 4	18° W 41.98 feet 1 ft. E of anch. pole
Metal Survey Sign Post S 2	5 ⁰ W 43.55 feet
NOTE: All bearings are magnetic bearings. All distances are measured with stee	el tape. Distances to trees are to nail in side of tree.
Signed by William Fina Date	e Nov. 2, 1999
Surveyor's Michigan License No. 26461	
26461	

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of 1990 On 199