ANTE DESCRIPTION

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of 1990 On 189 P.A. Of 1990 On ___

	MAR 29 2000	÷			Land Surv Peer Gro	ey Remonumer ip Under Act 3	ntation
		LAND CORNER RECOR			P.A. Of 1990 On	10/1	_ 1992
For corners in	SECTION	LAND CORNER RECOR Filing Requirement of A	CCT 74. Mich P.A.	IFICATE	MEC	Siavis Chairman	BL5
MENOMINEE		. 1		i. 1970	BK. 6		
(County)	Located In:	Corner Code #			1	Ps-	102
1. Public Land Sur	Trov.	·		}		FOR RECOR	
W 45110 Edild Sui	т <u>т</u> _3	85NR 27W F-3	-		28 DEC 199	9 3:56:09	PM
ĺ	· T_	R			BARBAR	MUDD took	
2. Property Control	lling S T					OF DEEDS MI 49858	
in Section	s t_	- K					
 Miscellaneous Property in Sec. 	ST		 [
,, 000.	s 「	_ R	_				
4 Lot No	D		Ĺ	Re	ister of Deeds	Stamp & F	ile Numbe
5. Private Claims	Recorded Plat						
~		•		1 A B	CDEF	G H I	JKL
				2 6			
i, William Lenca	in a field survey	on Oct. 1999 do h		3		11	
conformance with regulation						10	-11-12
that the corner points	of the interior, Bureau of La	nd Management or by a deare	Agy matructions of the	, 3	++++		++1
Board of Land Surveyors	or by a Decree of a Cou	nd Management or by a decree of a pove were in conformance with the art of Law; established, re-established	rules of the Michigan	6 -18 7 -	17-16-	15	14-13-
Transition and exples	sea below.	, re-estable	isned, monumented,	6 19	 	 	+++
On this certifice	2 comers, all in the same:	town and range, may be record	ed	9	-20-1-21-	22	2324
	ic.			10 -30-	29 28	† † †-	+++-
				11		2/2	2625
_				12 -31-	3233	-34 3	
A. Description of origina	al monument and access	ories and/or subsequent resto		13			J 36
1848: Sectional S	ubdivision by James II	Mullett - B.T.'s - Tamarack, is been destroyed by county r		lks.; Cedar s.	, 5" - S51°W -	14 lks. All	I
		•.	₹	٠			
B. Description of corner	evidence found and/or w	a adds t					
We found a P K Nai	in the sent of	nethod applied in restoring or r	eestablishing com	er:			
fence and the distance	Shot and the short and the sho	North - South County Road, in mile West is 2652.33 feet. Kazianka, documents that the to establish the position of the but fits well with long standal corner.	position of this D	17 TIME E.	ast to an ancier	it 1/16 fence ith the 1/10 measurement in the 1/10 measurement in the state of the	er se is sent
Description of monumer	nt for corner and accesso	ories established to perpetuate	locating the past		annanda **	LENCA LAND SURVEYOR	*
Set 5/8" x 24" Iron Roo	1/3-1/4" dia. Alum. cap	stamped for corner location i	n Monumer	יויט נוע the co	ner:	No. 26461	
3/8" X 24" Iron Ro	d/2" dia 11		т татотиппісці Вох	:	Var III	en caun Si	W. Title
5/8" x 24" Iron Rod	/2" dia. Alum, cap mark	rked "WITNESS MARKER" sed "WITNESS MARKER"		.99 feet	1 ft. E of pov	Sentantico	Dare.
18" dia. White Ash 5/8" x 24" Iron Rode	/2" dia - 41	""" INDO WAKKER"	East 31	.52 fect	@ sign post	res pose	
Metal Survey Sign F	² ua. Alum, cap mark ² ost	ed "WITNESS MARKER"	37000-	67 feet 13 feet	Scr. NBT		
					.65 ft, E of A	nch pole	
An ocarings are	e magnetic bearings. Al	ll distances are measured wit	h steel tane Diet	20000 += +			
ined by All	n From		who. Digi	mices to the	es are to nail in	side of tree	е.
rveyor's Michigan License I	No.		DateNov.	2, 1999			
	26461						·