STATE OF MICHIGAN DEPARTMENT NATURAL RESOURCES

LAND CORNER RECORD

		Menominee COUNTY
		T <u>35 N</u> R <u>28 W</u>
DESCRIPTION OF CORNER	Section corner for Sections	<u>4/3</u> 9/10
CORNER MONUMENT	1%" x 30" iron pipe buried	in east-west gravel road
DATE MONUMENT PLACED AND WITNESSED 1/20/71 F. J. Bray		
WITNESSES TO CORNER 24" White Pine S 610 5. 47.51		
N 0 10	8" Tamarack S 54°W, 31.91	
	Iron rail gate post, South,	49.31
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed in & of the east-west gravel road and in line with the fence line to the south and a down fence line to the north. Resident, Mr. Broberg recalls the corner to be at this location.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED FREGISTERED LAND SURVEYOR DATE 6-23-71

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68