## LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in	Filing Re	equirement of Act 74, Mich. P	P.A. 1970									
	Menominee	Located In:	Corner Code ≠										
	(County)	Located in .:	,										
1.	Public Land Survey	T <u>35N</u> R <u>2</u> T R T R											
2	Property Controlling	TR											
۷.	in Section	S T R S T R											
3.	Miscellaneous	S T R				_		_					
_	Property in Sec.	S T R		Regist	er of	Dee	ids S	itam	ip &	File	Nun	nber	
A	Lot No.	Decorded Dist											_
5.	Private Claims	recorded Fiai			A E	C	D	E F	G	н	1 1	к	L
-				2	<u>-</u>	4	- <b>j</b>	<del></del> ↓↓		- j - 3—	<u>                                     </u>		- [ - [
				3	$\downarrow$		1			Ĺ	ЦĬ		Ĺ
_	David Babbitt		10/10 00	•	₁ <mark>├</mark> ╶┤	$\bot$	ــــــ إ	μļ	$\bot$	-10—	<u> </u>	,_	-   - 12
•• -	<del></del>	in a field survey on	10/10 , 19 88	,	·├─┼		┿	$\vdash \downarrow$	-	↓_	₩	$\dashv$	4
in i Cur Mai abo	lines 1 and 2 above were in trent manual of survey instru- nagement or by a decree of a ove were in conformance with	n conformance with regulation uctions of the United States D a Court of Law and/or that the c th the rules of the Michigan Bo	n P.A. of 1970, the corner points mentions and rules therefore as required in epartment of the Interior, Bureau of I corner points mentioned in lines 3, 4 a pard of Land Surveyors or by a Decree re-monumented, recovered, found	n the Land <sup>7</sup> and 5 a	19	+	1/7	16 21		22—		; <del></del>	-13 -24
exp	pressed below:	o ostabilotica, monamentes,	re-monumented, recovered, touri	u as 10	30	丄	.29			27_		L	1
NO	TE: Not more than 4 c	orners, all in the same tow	n and range, may be recorded	11	LĪ	$\bot$		ΙĨ	$\perp$	Ĭ.	Lì		Ī
	on this certificate.		• • • • • • • • • • • • • • • • • • • •	12	31-	上	32	33		34			36-
	Description of arial-state			13		丄	Ī	يَ	Щ	1	ЦÏ	$\perp$	Ĭ
٠.			and/or subsequent restoration:										
·—'	7. N 1/4 corner o	of Section 20. Woo	od post, 1852. Balm of	Gilead	5 N6 6 S1	OW, 5E,	, 6 , 14	Iks III	3. KS.				
C-9	9. SW section co: 1949 but no de	mer of Section 20. escription of corne	Position indicated or monument or witnesse	n drawin	g by	R.	OJ	.sor	ı dı	:aw	n i	n	

- D-9. S 1/4 corner of Section20. Wood post, Sept. 1852. Tam. 10, N61W, 14 Lks. Oedar 20, S71E, 39 Lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- D-7. Set MPOL between the NW and NE section corners of Section 20. Corner falls on the north side of Shakey River.
- C-9. Set in g of E-W blacktop road by retracing R. Olson's 1949 survey. Falls nearly in line with old fence line running south from the road.
- D-9. Set MPOL between the SE and SW section corners of Section 20. OBT's would fall in roadway. Monument set flush with blacktop.
- C. \*Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7. 1" pipe w/DNR plug cap. C-9. DNR Monument D-9. Menominee Co. Monument 10" cedar, N73E, 22.05' 8" b.ash, S54E, 23.1' 8" j.pine, SlOW, 48.8' 4" cedar, S30E, 77.9' 10" oak, N5E, 37.0' 6" cedar, S44W, 75.3' 12" b./ash, S70W, 25.45' 14" oak, S50E, 94.9' 8" cedar, N7E, 53.2' 10" cedar, N41W, 54.9' 13" oak, N56W, 73.0' 10" cedar, N44E, 67.1'

Surveyor's Michigan License No. \_