Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 36 N.R. 24W

DESCRIPTION OF CORNER ______ E 1/16 corner for sections $\frac{8}{17}$ CORNER MONUMENT ______ 1½" x 30" iron pipe placed 06 lks. south of center line dirt road.

DATE MONUMENT PLACED AND WITHESSED ______ 12/15/67 Frank J. Bray

WITHESSES TO CORNER..... ½" Cedar (E 1/16) (BT) \$36° W, 14-3/4 lks.

7" Cedar (E 1/16) (BT) S 40° E, 134 lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

AND

CIRCLE CORNER REGISTERED

Placed on line and midway between section corner to East and 1/4 corner to west.

Location post, south, 03 lks.

SURVEYOR'S SEAL

Frank J. Bray DATE 2/1/68