

✓

**MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION**

# LAND CORNER RECORD

T. 36 N.R. 24W


Menominee COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{8}{9}$   
 $\frac{17}{16}$

CORNER MONUMENT 1½" iron pipe

DATE MONUMENT PLACED AND WITNESSED 11/28/67 Frank J. Bray

WITNESSES TO CORNER..... 12" Cedar (S 8) (NBT) N 29° W, 67 lks.



12" Cedar (S 9) (NBT) N 07° E, 38½ lks.

Fence corner south, 44 lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

Found by survey crew. Corner lies approximately 18 lks. north of centerline of E-W gravel road. Fence corner to south 44 lks. This corner witnessed by Michigan State Highway Department.

**SURVEYOR'S SEAL**

SIGNED Frank J. Bray DATE 2/1/68  
REGISTERED LAND SURVEYOR  
Frank J. Bray