

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 36 N. R. 24W


Menominee COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{19}{20}$   $\frac{30}{29}$

CORNER MONUMENT 1½" iron pipe

DATE MONUMENT PLACED AND WITNESSED 5/17/68, F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (S.19) (NBT) N 75° W, 27½ links



6" Cedar (S.29) (NBT) S 78° E, 26 links

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was found iron pipe which was rewitnessed by Mich. Highway Dept. in 1948. Two old wood post at corner. Old Blazes and signature tree near. Rotted down cedar to SE possible B.T.

**SURVEYOR'S SEAL**

SIGNED Frank J. Bray DATE 7/11/68  
REGISTERED LAND SURVEYOR  
Frank J. Bray