

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 36 N.R. 'S 24 & 25W


Menominee COUNTY

DESCRIPTION OF CORNER Section corner for sections T36N, R25W ^{13/18} 24/19 T36N, R24W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 5/21/68, F. J. Bray

WITNESSES TO CORNER..... 10" Cedar (S. 18) (NBT) N 89° E, 06 links



12" Cedar (S. 24) (NBT) S 60° W, 30½ links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post which checks well with bearings and distances to four rotted cedar stumps. Blazed trees in vicinity. Cedar to SE has axe marks on it.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/11/68
REGISTERED LAND SURVEYOR
Frank J. Bray