STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	T 36 N R 24 W
DESCRIPTION OF CORNER East 1/16 corner for Section	5 ons 8
CORNER MONUMENT 1½" x 30" iron pipe buried	in logging road
DATE MONUMENT PLACED AND WITNESSED 1/21/71 F. J. B.	гау
WITNESSES TO CORNER 12" Gedar (E 1/16) (BT) S }	13 ⁰ E, 29.21
6" W. Birch (BT) S 76°W, 1	13.31
AND CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corner to the

east and the 1/4 corner to the west.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE

6-23-71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047

Rev. 10/68