## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.36. NR -25. W. T 37 NR 25 W

			MengminesCOUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 2,3,34,35
DESCRIPTION	OF	CORNER	MONUMENT_1" Pips with A" Brass sap
WITTNESSES	то	CORNER	_ 8% Belsam = H 74_E = 20 Links
			_ 8"_Coder - S_5_W 11 Links
			14" Cedar - N 30 W - 28 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by Clarence Limpert, District Forester, of Escanaba. Three original B.T.'s still in place, in good condition.

Corner was placed and witnessed March 15, 1951.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 4/2/51