

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

✓
✓

LAND CORNER RECORD

T. 36 N. R. 25


Menominee COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections $\frac{1}{12}$

CORNER MONUMENT 1" iron pipe with 4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/11/67, Frank J. Bray

WITNESSES TO CORNER..... 7" Cedar (1/4S)(NBT) N 89° W, 24 $\frac{1}{2}$ Links



9" Cedar (1/4S)(NBT) N 83° E, 03 $\frac{1}{2}$ Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed midway and on line between section corners to east and west. Squared cedar and ~~in~~ blazes near. No original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/8/67
REGISTERED LAND SURVEYOR